

Dmb

JUL 10 1985

Docket No. 50-409

Dairyland Power Cooperative
ATTN: Mr. F. W. Linder
General Manager
2615 East Avenue - South
La Crosse, WI 54601

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. Snell and others of this office on June 24-26, 1985 of activities at the La Crosse Boiling Water Reactor authorized by NRC Operating Licenses No. DPR-45 and to the discussion of our findings with Messrs. J. Parkyn, T. Steele and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

However, weaknesses were identified which will need corrective action by your staff. These weaknesses are summarized in the attached Appendix to this letter. As required by 10 CFR Part 50, Appendix E, IV.F, any weaknesses that are identified must be corrected.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W. D. Shafer, Chief
Reactor Projects Branch 2

Enclosures:

1. Appendix, Notice
of Violation
2. Inspection Report
No. 50-409/85009(DRP)

See Attached List For Distribution

8507150466 850710
PDR ADOCK 05000409
Q PDR

IE01
11

Dairyland Power Cooperative

2

JUL 10 1985

cc w/enclosures:

J. Parkyn, Plant Superintendent

DMB/Document Control Desk (RIDS)

Resident Inspector, RIII

John J. Duffy, Chief

Boiler Section

Ness Flores, Chairperson

Wisconsin Public Service

Commission

Spark Burmaster, Coulee

Region Energy Coalition

RIII
RWD
DeFayette/cs
07/09/85

RIII
1/1/86
Ridgway

RIII
del
Boyd

RIII
mail for
Lanksbury

RIII
web/for
Shafer