

October 17, 1996

Stephen Bindon
Trijicon, Inc.
49385 Shafer Ave.
Wixom, MI 48393

Dear Mr. Bindon:

This letter is in reference to our telephone conversations on August 1, 1996, and September 20, 1996, regarding data on failure types and rates for Trijicon's tritium gunsights, and information regarding your recommended mounting procedures.

The information requested will be used to determine whether there are any generic trends that can be identified in the failures of tritium pistol and rifle gunsights, and will look into areas such as, whether any identifiable trends point to design, mounting, mounting procedures, or misuse as a contributing factor in the failures, and whether there is any trend in the statistics to show that the failures were primarily due to a single cause or were randomly distributed.

We would appreciate your assistance in obtaining this information. Please provide the requested information within thirty (30) days of the date of this letter. If you have any questions, please contact me at (301) 415-5868 or Mr. Steven Baggett at (301) 415-7273.

Sincerely,

Original Signed by

Michele L. Burgess, Mechanical Engineer
Sealed Source Safety Section
Medical, Academic, and Commercial
Use Safety Branch
Division of Industrial and
Medical Nuclear Safety
Office of Nuclear Material Safety
and Safeguards

Distribution:

SSSS r/f

NMSS r/f

NE01 *JA*

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	IMAB	<input checked="" type="checkbox"/>	IMAB	<input checked="" type="checkbox"/>					
NAME	MBurgess/mb <i>mb</i>		SBaggett						
DATE	10/17/96		10/17/96						

OFFICIAL RECORD COPY

9610240082 961017
PDR RC * PDR
SSD