



Carolina Power & Light Company
P.O. Box 10429
Southport, NC 28461-0429

OCT 14 1996

SERIAL: BSEP 96-0361

U. S. Nuclear Regulatory Commission
ATTENTION: Mr. Stewart D. Ebnetter, Regional Administrator
101 Marietta Street, N.W., Suite 2900
Atlanta, GA 30323-0199

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 AND 2
DOCKET NOS. 50-325 AND 50-324/LICENSE NOS. DPR-71 AND DPR-62
NRC INSPECTION REPORT NOS. 50-324/96-04 AND 50-325/96-04
UNIT 2 MOISTURE SEPARATOR REHEATER MANWAY WELDS

Mr. Ebnetter:

In Inspection Report Nos. 50-324/96-04 and 50-325/96-04, the U.S. Nuclear Regulatory Commission (NRC) documented inspection activities pertaining to the Brunswick Steam Electric Plant, Units 1 and 2. Section 4.1 in this report discussed replacement of the "B" low pressure turbine rotor and included a statement that all welders who performed work on the turbine during this outage were appropriately trained and certified to weld and perform work to the appropriate procedures. Carolina Power & Light Company would like to clarify this statement by noting that all welders who were involved with this work, with the exception of the one non-certified welder discussed in our August 15, 1996 letter, were appropriately trained and certified to weld and perform work to the appropriate procedures.

Please refer any questions regarding this submittal to Mr. Mark A. Turkal at (910) 457-3066.

Sincerely,

William Levis
Director — Site Operations
Brunswick Nuclear Plant

WRM/wrm

9610240108 961014
PDR ADOCK 05000324
Q PDR

IED 1/0

Document Control Desk
BSEP 96-0361 / Page 2

cc: U. S. Nuclear Regulatory Commission
ATTN.: Document Control Desk
Washington, D.C. 20555

Mr. C. A. Patterson
NRC Senior Resident Inspector - Brunswick Units 1 and 2:

U.S. Nuclear Regulatory Commission
ATTN.: Mr. David C. Trimble, Jr. (Mail Stop OWFN 14H22)
11555 Rockville Pike
Rockville, MD 20852-2738

The Honorable H. Wells
Chairman - North Carolina Utilities Commission
P.O. Box 29510
Raleigh, NC 27626-0510