



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV  
URANIUM RECOVERY FIELD OFFICE  
BOX 25325  
DENVER, COLORADO 80225

DATE: 3/21/83

NOTE TO  
DOCKET FILE: 40-8745

FROM: *Yvonne Young*

SUBJECT: REVIEW OF MAIL CONTROL NO. 00106

I have reviewed the subject document and have concluded the following:

- \_\_\_\_\_ This document contains information that is not essential to the review and maintenance of this license and no further regulatory review or consideration is warranted.
- \_\_\_\_\_ This document contains information that was previously submitted and reviewed and no further action is warranted.
- \_\_\_\_\_ This document contains substantive information that is summarized below; however, no further regulatory action is warranted.
- ☒ This document contains substantive information that is summarized below and is essential to the review and maintenance of this license. Further regulatory review or consideration is necessary.

SUMMARY: The materials Radiation section, Region IV  
is responsible for review of all ALARA  
audit reports.

DATE DUE TO DOCKET FILE:

*DWG for JTL*