

October -5, 1996

Dr. John A. Bernard, Jr.
Director of Reactor Operations
Massachusetts Institute of Technology
Research Reactor
MITNRL-NW12
138 Albany Street
Cambridge, MA 02139

SUBJECT: NRC INSPECTION NO. 50-20/96-02

Dear Dr. Bernard:

On September 20, 1996, the NRC completed a one week operations inspection at the MIT research reactor. The enclosed report represents the results of that inspection.

No noncompliances or significant issues were identified. No response to this letter is required.

Your cooperation with us is appreciated.

Sincerely,

John R. White, Chief
Radiation Safety Branch
Division of Reactor Safety

Docket No. 50-20
License No. R-37

Enclosure: NRC Region I Inspection Report No. 50-20/96-02

cc w/encl:

Dr. O. K. Harling, Director of the Reactor Laboratory
Dr. William Vernetson, TRTR
Dr. Robert McCunney, M.D., Director, Environmental Medical Service
Commonwealth of Massachusetts

240005

9610240237 961005
PDR ADOCK 03000020
G PDR

1201
11

Dr. John A. Bernard, Jr.

2

Distribution w/encl:

Region I Docket Room (with concurrences)

S. Weiss, NRR (OWFN 10D21)

V. McCree, OEDO (OWFN 17 G21)

D. Screnci, PAO (2)

PUBLIC

Nuclear Safety Information Center (NSIC)

DRS File

DOCUMENT NAME: G:\RSB\DRAGOUN\MIT96.02

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RI/DRS	E	RI/DRS		/				
NAME	TDRAGOUN		WHITE						
DATE	10/15/96		10/15/96		10/ /96		10/ /96		10/ /96

OFFICIAL RECORD COPY