

Commonwealth Edison Company
Byron Generating Station
4450 North German Church Road
Byron, IL 61010-9794
Tel 815-234-5441



September 24, 1996

LTR: BYRON-96-5155

FILE: 3.11.0530

Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

ATTENTION: Document Control Desk

SUBJECT: ComEd Byron Station Unit 1 Steam Generator Eddy Current
Examination During B1R07 - 90 Day Summary Report

Byron Nuclear Power Station, Unit 1
Facility Operating License PF-37
NRC Docket No. 50-454

REFERENCE: LER 454: 96-003
BYRON-96-5081

Please find attached a report for the Byron Unit 1 Steam Generator examination performed during Cycle 7 refueling outage (B1R07) during April-June 1996. This report is being submitted in compliance with the requirements of Mandatory Appendix IV of Section XI of the ASME Boiler and Pressure Vessel Code, 1983 Edition through Summer 1983 Addenda in accordance with Byron Technical Specification 4.0.5.

300093

A047
11


9609300311 960924
PDR ADOCK 05000454
Q PDR

A Unicom Company

BYRON-96-5155

If there are any additional questions, please contact Marcia Lesniak, Nuclear Licensing Administrator at (630)663-6484.

Sincerely,



David B. Wozniak
Site Engineering Manager
Byron Nuclear Power Station

DBW/cb

Attachment

cc: A. B. Beach, NRC Regional Administrator, RIII
G. F. Dick, Jr., Byron Project Manager - NRR
Sonia Burgess, Senior Resident Inspector, Byron
Office of Nuclear Safety - IDNS