

Commonwealth Edison Company
Byron Generating Station
4450 North German Church Road
Byron, IL 61010-9794
Tel 815-234-5441



October 1, 1996

LTR: BYRON-96-1160

FILE: 3.11.0321

Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

ATTENTION: Document Control Desk

SUBJECT: ComEd Byron Station Unit 1 Inservice Inspection Report for Interval 1,
Period 3, Outage 3 (B1R07)

Byron Nuclear Power Station, Unit 1
Facility Operating License PF-37
NRC Docket No. 50-454

Please find attached a report for the Byron Unit 1 Inservice Inspections performed during Cycle 7 refueling outage (B1R07) during April-June 1996. This report is being submitted in compliance with the requirements of Article IWA-6000 of Section XI of the ASME Boiler and Pressure Vessel Code, 1983 Edition through Summer 1983 Addenda in accordance with Byron Technical Specification 4.0.5.

If there are any additional questions, please contact Marcia Lesniak, Nuclear Licensing Administrator at (630)663-6484.

Sincerely,

David B. Wozniak
Site Engineering Manager
Byron Nuclear Power Station

CBW/cb

Attachment

cc: A. B. Beach, NRC Regional Administrator, RIII
G. F. Dick, Jr., Byron Project Manager - NRR
Sonia Burgess, Senior Resident Inspector, Byron
Office of Nuclear Safety - IDNS

000000

9610040036 961001
PDR ADOCK 05000454
Q PDR