

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

July 8, 1985

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: McGuire Nuclear Station, Unit 2
Docket No. 50-~~370~~

Gentlemen:

On June 1, 1985 McGuire Unit ² experienced a reactor trip due to an apparent ground on the doghouse level switches. During the investigation, it was determined that severe corrosion in an area termination cabinet contributed to the trip. Due to some of the planned corrective actions being completed following a subsequent trip, this report has been delayed and will be submitted by July 17, 1985.

Very truly yours,

H.B. Tucker

Hal B. Tucker

JBD/mjf

cc: Dr. J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

M&M Nuclear Consultants
1221 Avenue of the Americas
New York, New York 10020

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange, Suite 245
270 Farmington Avenue
Farmington, CT 06032

8507170480 850708
PDR ADOCK 05000370
S PDR

A001
1/0