

TRUMBULL CORPORATION

P. O. Box 98100
Pittsburgh, PA 15227
Telephone 412/462-9300

May 29, 1985

U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Attention: Mr. John D. Kinneman, Chief
Nuclear Materials Safety Section A,
Division of Radiation Safety and Safeguards

Re: Inspection Report No. 85-01
License No. 37-19062-01
Docket No. 030-16010

Gentlemen:


Regarding the storage area location of our material, we have relocated the material in a storage room in the same building where the inspection was conducted. There is no direct contact with any employees in this room. Also, employees are separated from this room by 8 inch concrete block walls. Mrs. T. Hall Darden visually inspected this area and found it suitable as a storage location. The relocation was done on February 26, 1985 following the inspection.

Regarding the notice of violation in Appendix A, the person in question, Mr. Paul Yuran, attended the Troxler Laboratory Training Course on September 10, 1984. Due to lack of communication on our part, Mr. Yuran's Certificate was not sent to you until February 5, 1985. It is likely that you did not receive our letter before your inspection on February 26, 1985. I hope that this explanation is a satisfactory correction to the violation. We now understand that any future employees will not be permitted to use guages until an amendment to our license is completed with the persons name appearing on the license.

If you have any questions regarding the above information, please do not hesitate to contact me.

Very truly yours,

TRUMBULL CORPORATION


Michael A. Bianco

8507170533 850628
REQ1 LIC30
37-19062-01 PDR

MAB/mrm



91-2-ND 8-100 8861
RECEIVED-REG-1