

# OPERATING DATA REPORT

DOCKET NO. 50-237

DATE July 1, 1985

COMPLETED BY D. C. Maxwell

TELEPHONE 815/942-2920

## OPERATING STATUS

1. Unit Name: Dresden II
2. Reporting Period: June, 1985
3. Licensed Thermal Power (MWt): 2,527
4. Nameplate Rating (Gross MWe): 828
5. Design Electrical Rating (Net MWe): 794
6. Maximum Dependable Capacity (Gross MWe): 812
7. Maximum Dependable Capacity (Net MWe): 772
8. If Changes Occur in Capacity Ratings (Items 3 Through 7) Since Last Report, Give Reasons:

## NOTES

N/A

9. Power Level to Which Restricted, If Any (Net MWe): N/A
10. Reasons For Restrictions, If Any: N/A

	This Month	Yr-to-Date	Cumulative
11. Hours in Reporting Period	720	4,343	132,647
12. Number of Hours Reactor Was Critical	591.8	1,714.6	100,450.5
13. Reactor Reserve Shutdown Hours	0	0	0
14. Hours Generator On-Line	544.0	1,537.1	98,846.9
15. Unit Reserve Shutdown Hours	0	0	0
16. Gross Thermal Energy Generated (MWH)	1,142,019	3,139,363	149,477,421
17. Gross Electrical Energy Generated (MWH)	357,496	986,622	62,207,963
18. Net Electrical Energy Generated (MWH)	337,733	921,633	58,770,259
19. Unit Service Factor	76.6	35.4	74.5
20. Unit Availability Factor	75.6	35.4	74.5
21. Unit Capacity Factor (Using MDC Net)	60.8	27.5	57.4
22. Unit Capacity Factor (Using DER Net)	59.1	26.7	55.8
23. Unit Forced Outage Rate	24.4	17.6	11.3
24. Shutdowns Scheduled Over Next 6 Months (Type, Date, and Duration of Each): Snubber inspection on October 12, 1985 ± 4 weeks.			

25. If Shut Down At End Of Report Period, Estimated Date of Startup: N/A

8507180294 850630  
PDR ADOCK 05000237  
R PDR

IE24  
1/1

# OPERATING DATA REPORT

DOCKET NO. 050-249

DATE July 1, 1985

COMPLETED BY D. C. Maxwell

TELEPHONE 815/942-2920

## OPERATING STATUS

### NOTES

1. Unit Name: Dresden III
2. Reporting Period: July 1, 1985
3. Licensed Thermal Power (MWt): 2,527
4. Nameplate Rating (Gross MWe): 828
5. Design Electrical Rating (Net MWe): 794
6. Maximum Dependable Capacity (Gross MWe): 812
7. Maximum Dependable Capacity (Net MWe): 773
8. If Changes Occur in Capacity Ratings (Items 3 Through 7) Since Last Report, Give Reasons:

N/A

9. Power Level to Which Restricted, If Any (Net MWe): N/A
10. Reasons For Restrictions, If Any: N/A

	This Month	Yr-to-Date	Cumulative
11. Hours in Reporting Period	720	4,343	122,232
12. Number of Hours Reactor Was Critical	720.0	4,094.7	93,972.7
13. Reactor Reserve Shutdown Hours	0	0	0
14. Hours Generator On-Line	720.0	4,022.0	87,194.1
15. Unit Reserve Shutdown Hours	0	0	0
16. Gross Thermal Energy Generated (MWH)	1,702,449	9,188,426	176,245,449
17. Gross Electrical Energy Generated (MWH)	534,570	2,915,517	57,122,494
18. Net Electrical Energy Generated (MWH)	508,517	2,776,729	54,112,957
19. Unit Service Factor	100.0	92.6	71.3
20. Unit Availability Factor	100.0	92.6	71.3
21. Unit Capacity Factor (Using MDC Net)	91.4	82.7	57.3
22. Unit Capacity Factor (Using DER Net)	89.0	80.5	55.8
23. Unit Forced Outage Rate	0	6.7	12.5
24. Shutdowns Scheduled Over Next 6 Months (Type, Date, and Duration of Each):			
Refueling and Recirculation Piping Replacement outage - Fall of 1985 for approximately six (6) months.			

25. If Shut Down At End Of Report Period, Estimated Date of Startup: N/A

## UNIQUE REPORTING REQUIREMENTS

### MAIN STEAM RELIEF VALVE OPERATIONS

Relief valve operations during the reporting period of June, 1985 are summarized in the following table. The table includes information as to which relief valve was actuated, how it was actuated, and the circumstances resulting in its actuation.

<u>Unit</u>	<u>Reporting Period</u>	<u>Valves Actuated</u>	<u>Actuations</u>	<u>Conditions</u>	<u>Description of Events</u>
2	06-01-85 to 06-30-85	None			
3	06-01-85 to 06-30-85	None			

COMMONWEALTH EDISON COMPANY

DRESDEN STATION

MAXIMUM DAILY LOAD

MONTH OF JUNE, 1985

DAY	HOUR ENDING	MAXIMUM DAILY LOAD KW
1	2400	1,386,400
2	2400	1,437,700
3	2400	1,507,700
4	1400	1,577,900
5	1100	1,572,100
6	2400	1,559,300
7	0100	1,558,600
8	0100	1,465,000
9	0100	1,059,300
10	2400	741,100
11	2100	786,200
12	2000	795,200
13	1200	795,800
14	2400	1,276,100
15	1400	1,278,000
16	2400	1,393,700
17	2400	1,574,300
18	1000	1,596,800
19	1200	800,400
20	1200	799,900
21	2000	1,284,400
22	2000	1,208,500
23	2400	1,280,300
24	2400	1,476,300
25	2400	1,571,800
26	0200	1,581,900
27	1300	1,583,100
28	1200	1,384,700
29	1300	1,370,700
30	2400	1,433,000
31	--	--

## UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH JUNE, 1985DOCKET NO. 050-237UNIT NAME Dresden IIDATE July 1, 1985COMPLETED BY D. C. Maxwell.TELEPHONE (815) 942-2920

NO.	DATE	TYPE <sup>1</sup>	DURATION (HOURS)	REASON <sup>2</sup>	METHOD OF SHUTTING DOWN REACTOR <sup>3</sup>	LICENSEE EVENT REPORT #	SYSTEM CODE <sup>4</sup>	COMPONENT CODE <sup>5</sup>	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
3	85-06-09	F	119:30 (119.5)	A	3	85-027-0	--	--	2B MG Set problems and snubber inspection, also Rx Mod switch problems caused by scram.
3	85-06-18	F	56.32 (56.5)	A	3	85-028-0	--	--	Rx scram because of high level in S.D.V.

1

F: Forced  
S: Scheduled

2

Reason:  
A-Equipment Failure (Explain)  
B-Maintenance or Test  
C-Refueling  
D-Regulatory Restriction  
E-Operator Training & License Examination  
F-Administrative  
G-Operational Error  
H-Other (Explain)

3

Method:  
1-Manual  
2-Manual Scram  
3-Automatic Scram  
4-Other (Explain)

4

Exhibit G-Instructions for  
Preparation of Data  
Entry Sheets for Licensee  
Event Report ( ) File  
(NUREG-0161)

## UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 050-249

UNIT NAME Dresden III

DATE July 1, 1985

COMPLETED BY D. C. Maxwell

TELEPHONE (815) 942-2920

REPORT MONTH JUNE, 1985

NO.	DATE	TYPE <sup>1</sup>	DURATION (HOURS)	REASON <sup>2</sup>	METHOD OF SHUTTING DOWN REACTOR <sup>3</sup>	LICENSEE EVENT REPORT #	SYSTEM CODE <sup>4</sup>	COMPONENT CODE <sup>5</sup>	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
	None								

1

F: Forced  
S: Scheduled

2

Reason:  
A-Equipment Failure (Explain)  
B-Maintenance or Test  
C-Refueling  
D-Regulatory Restriction  
E-Operator Training & License Examination  
F-Administrative  
G-Operational Error  
H-Other (Explain)

3

Method:  
1-Manual  
2-Manual Scram  
3-Automatic Scram  
4-Other (Explain)

4

Exhibit G-Instructions for  
Preparation of Data  
Entry Sheets for Licensee  
Event Report ( ) File  
(NUREG-0161)



# AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO. 50-237

UNIT II

DATE July 1, 1985

COMPLETED BY D. C. Maxwell

TELEPHONE 815/942-2920

MONTH JUNE, 1985

DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
1	<u>736</u>
2	<u>667</u>
3	<u>705</u>
4	<u>750</u>
5	<u>748</u>
6	<u>749</u>
7	<u>714</u>
8	<u>548</u>
9	<u>116</u>
10	<u>0</u>
11	<u>0</u>
12	<u>0</u>
13	<u>0</u>
14	<u>207</u>
15	<u>448</u>
16	<u>554</u>

DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
17	<u>683</u>
18	<u>517</u>
19	<u>0</u>
20	<u>0</u>
21	<u>240</u>
22	<u>428</u>
23	<u>458</u>
24	<u>594</u>
25	<u>714</u>
26	<u>731</u>
27	<u>772</u>
28	<u>758</u>
29	<u>768</u>
30	<u>611</u>
31	<u>---</u>

# AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO. 50-249

UNIT III

DATE July 1, 1985

COMPLETED BY D. C. Maxwell

TELEPHONE 815/942-2920

MONTH JUNE, 1985

DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
1	<u>506</u>
2	<u>652</u>
3	<u>735</u>
4	<u>735</u>
5	<u>741</u>
6	<u>734</u>
7	<u>732</u>
8	<u>707</u>
9	<u>682</u>
10	<u>705</u>
11	<u>734</u>
12	<u>754</u>
13	<u>752</u>
14	<u>712</u>
15	<u>736</u>
16	<u>708</u>

DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
17	<u>723</u>
18	<u>752</u>
19	<u>767</u>
20	<u>759</u>
21	<u>763</u>
22	<u>679</u>
23	<u>674</u>
24	<u>749</u>
25	<u>737</u>
26	<u>712</u>
27	<u>737</u>
28	<u>677</u>
29	<u>534</u>
30	<u>714</u>
31	<u>---</u>



DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
MSL Hi Rad Comp. Pt.	Preventive W.R. #34259	---	N/A	N/A	Jumpered appropriate points - correct alarms came up.
CRD Module 22-07	Corrective W.R. #38927	---	N/A	N/A	Replaced accumulator.
Inboard "B" MSIV Air Supply, AO-2-203-1B	Corrective W.R. #40237	---	N/A	N/A	Changed old air cylinder and "E" and "D" seal rings.
Feedwater Inboard "B" Feedcheck 2-220-58B	Corrective W.R. #40271	---	N/A	N/A	Replaced seal and dish on feedwater check valve.
24/48 Bt. Bottar Charger	Preventive W.R. #40278	---	N/A	N/A	Temperature external battery used to pick-up relay.
U2 LPCI Relay 1530-109	Preventive W.R. #40335	---	N/A	N/A	Picked up voltage checked.
Local Accumulator Alarm Indicating Panel	Preventive W.R. #40368	---	N/A	N/A	Replaced water filled switch.
Primary Contain- ment (Relay 595- 105AX	Preventive W.R. #40370	---	N/A	N/A	Replaced coil assembly and adjusted relay.
LPCI Sys. I 1530- 133 (BU) Time Delay Relay	Preventive W.R. #40398	---	N/A	N/A	Adjusted and cleaned relay.
Second Contain- ment Penetration	Corrective W.R. #40431	---	N/A	N/A	Installed new valve stem - cleaned valve.
D2 202-A Recirc. PP Decon Flange	Preventive W.R. #40435	---	N/A	N/A	Installed blind flange.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
"B" Recirc. Suction Line Supports 202-B-M-1201/103/104/105	Corrective W.R. # 40452	---	N/A	N/A	Tightened bolts.
2A-202-W-102 & 106 Recirc. Pump Supports	Corrective W.R. #40473	---	N/A	N/A	Tightened bolts.
D2 Personnel Door	Preventive W.R. #40522	---	N/A	N/A	Installed new gasket.
2-203-B Recirc. PP Decon.	Preventive W.R. #40531	---	N/A	N/A	Installed blind flange.
D022 1600 MISC-MOI Personnel Access Hatch	Corrective W.R. #40565	---	N/A	N/A	Installed new gasket and strong back on inner door.
AO-2-1601-21 Purge Valve	Corrective W.R. #40548	---	N/A	N/A	Installed new gasket.
D2 "C" Electromatic Valve 103	Corrective W.R. #40649	---	N/A	N/A	Replaced cracked nipple.
Clean-up Line 1201 Support 1201-M-101	Preventive W.R. #40667	---	N/A	N/A	Clamp removed.
Pratt Vent Valves 2-1601-23	Corrective W.R. #40689	---	N/A	N/A	Installed new torque factors - attached MOD proc.
Pratt Vent Valve 2-1601-56	Preventive W.R. #40690	---	N/A	N/A	Stacked and installed keylock.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
Pratt Vent Valve 2-1601-22	Corrective W.R. #40691	---	N/A	N/A	Replaced bolts, stacked and torqued.
Pratt Vent Valve 2-1601-21	Preventive W.R. #40692	---	N/A	N/A	Replaced screws, welded keystack.
Pratt Vent Valve 2-1601-20B	Preventive W.R. #40693	---	N/A	N/A	Replaced bolts, welded keystack.
Pratt Vent Valve 2-1601-20A	Preventive W.R. #40694	---	N/A	N/A	Replaced bolts, welded keystack.
Pratt Vent Valve 2-1601-63	Corrective W.R. #40695	---	N/A	N/A	Changed bolts and torqued - installed keystack.
Pratt Vent Valve 2-1601-60	Preventive W.R. #40696	---	N/A	N/A	Changed bolts and torqued - installed keystack.
Pratt Vent Valve 2-1601-24	Corrective W.R. #40697	---	N/A	N/A	Valve was not exposed - torqued.
MO-2-1501-3A	Preventive W.R. #40717	---	N/A	N/A	Everything ok.
CCSW Vault Strongback Door	Preventive W.R. #40738	---	N/A	N/A	Installed strongback on door.
CCSW Vault Floor Drain	Corrective W.R. #40752	---	N/A	N/A	Unplugged drain.
U2 D/G Cooling H.O. Discharge	Corrective W.R. #40763	---	N/A	N/A	Tightened support nut and pipe.
U2 Bustie Breakers	Preventive W.R. #40784	---	N/A	N/A	Installed and removed jumpers.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
2B Squib Valve 2-1106B	Preventive W.R. #40890	---	N/A	N/A	Replaced squib valve.
Constant Spring Hanger	Preventive W.R. #40925	---	N/A	N/A	Moved and replaced spring hanger - cleaned valve.
D/W Air Sample Valve AO2-8501- 1A	Corrective W.R. #40934	---	N/A	N/A	Cleaned valve.
D/W Sample Valve AO2-9206A	Corrective W.R. #40935	---	N/A	N/A	Cleaned valve.
2A D/G Starting Air Comp.	Preventive W.R. #40961	---	N/A	N/A	Replaced switch.
U2 Emergency Diesel Generator	Corrective W.R. #40983	---	N/A	N/A	Replaced line and union on pipe.
Panel 902-36	Preventive W.R. #41021	---	N/A	N/A	Replaced all power cables.
U2 305-111 Accumulator 50-39 N-10	Corrective W.R. #41060	---	N/A	N/A	Replaced ring.
Bellows Seal Penetration X-107A	Corrective W.R. #41121	---	N/A	N/A	Drilled, re-cut and rebent tubing into place.
Refuel Platform	Corrective W.R. #41123	---	N/A	N/A	Adjusted limits.
4KV Breaker 2302	Corrective W.R. #41131	---	N/A	N/A	Replaced SBM switch.
Beam Brace on Line 2-1201-8"	Preventive W.R. #41135	---	N/A	N/A	Replaced I-Beam, replaced D/W air lines.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
Torus Aerial Paint	Corrective W.R. #41152	---	N/A	N/A	Spot cleaned and painted.
Fuel Assembly	Preventive W.R. #41180	---	N/A	N/A	Removed and drilled stud - re-tapped hole.
2-2001-3 Valve	Corrective W.R. #41182	---	N/A	N/A	Replaced broken oiler.
Main Steam Line 3001A Weld #8X-3	Preventive W.R. #41186	---	N/A	N/A	Stroke tested snubber.
D2 Startup Hydro	Preventive W.R. #41188	---	N/A	N/A	Calibrated gauge.
Refuel Grapple	Corrective W.R. #41190	---	N/A	N/A	Installed new air and hose fittings.
U2 Scram Valves CU2-0305-126 and 127	Preventive W.R. #41191	---	N/A	N/A	Sprayed and exercised micro switch boots.
125VDC Ground	Corrective W.R. #41221	---	N/A	N/A	Cleaned relay.
Valve #2-5499- 71B	Corrective W.R. #41281	---	N/A	N/A	Cleaned valve.
SPM #21, 2-750- 1A	Preventive W.R. #41290	---	N/A	N/A	No problems found.
APRM Channel #3	Preventive W.R. #41302	---	N/A	N/A	Replaced burnt-out light bulb.
LPCI 2B-1503 Heat Exchanger	Corrective W.R. #41341	---	N/A	N/A	"Non-Safety" related.
Snubbers (3)	Preventive W.R. #41371	---	N/A	N/A	Disassembled snubbers for inspection.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
Main Steam Line 3001D, Weld #20-K14	Preventive W.R. #41450	---	N/A	N/A	Indications removed.
LPCI Line 1504 Snubber Clamp 1527	Preventive W.R. #41647	---	N/A	N/A	Removed and installed pipe clamp.
Accumulator #26-03	Corrective W.R. #41658	---	N/A	N/A	Replaced CRD accumulator - replaced O-ring.
1501-28A and 1501-27A	Preventive W.R. #41719	---	N/A	N/A	Removed drain line and flange and connected 4" compressor discharge pipe.
IRM Channel #12	Preventive W.R. #41768	---	N/A	N/A	Installed tubing sleeve.
SRM #22	Preventive W.R. #41769	---	N/A	N/A	Replaced extension cable and guard.
2-1402-17B Core Spray PP CST Drain Valve	Corrective W.R. #41827	---	N/A	N/A	Installed pipe cap.
FT-2-1461A Core Spray Flow Trans.	Preventive W.R. #41907	---	N/A	N/A	Inspected - no repairs.
FT-2-1461B Core Spray Flow Trans.	Preventive W.R. #41908	---	N/A	N/A	Inspected - no repairs.
PT-2-1460B Core Spray Pressure Trans.	Preventive W.R. #41910	---	N/A	N/A	Inspected - no repairs.
LPCI Flow Trans. FT-2-1542A	Preventive W.R. #41920	---	N/A	N/A	Inspected - no repairs made.



DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
LPCI Flow Trans. FT-2-1542B	Preventive W.R. #41921	---	N/A	N/A	Checked and cleaned trans.
FT-2-1549B LPCI Flow Trans.	Preventive W.R. #41923	---	N/A	N/A	Replaced bolts and cleaned trans.
2-1601, 33A-33B Torus to D/W Vacuum Breaker	Corrective W.R. #42158	---	N/A	N/A	Replaced rubber seat and cleaned.
2-1601, 33A-33B Torus to D/W Vacuum Breaker	Corrective W.R. #42159	---	N/A	N/A	Replaced seat and cleaned.
2-1601-32C and D Torus D/W Vacuum Breakers	Corrective W.R. #42160	---	N/A	N/A	Replaced seats and O-rings.
Rod Select Timer	Preventive W.R. #42293	---	N/A	N/A	Installed new timer.
LPRM 2A 16-33	Preventive W.R. #42340	---	N/A	N/A	Replaced light.
Hanger in HPCI Room	Corrective W.R. #42359	---	N/A	N/A	Turned clamp and re-tightened.
2-1705-8A Rx Bldg. Vent Rad Monitor	Preventive W.R. #42385	---	N/A	N/A	Cleaned contacts.
CRD L5	Preventive W.R. #42399	---	N/A	N/A	Removed and replaced support steel, rings and drive.
2-202-5	Preventive W.R. #42429	---	N/A	N/A	Installed and removed test rig.
2-2202-6 Rack	Preventive W.R. #42430	---	N/A	N/A	Installed and removed test rig.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
U2 RPS Relays 590-112A,B,C,D	Preventive W.R. #42462	---	N/A	N/A	Restored relays.
Welds #8-2 and 3 ISI Condenser Class 2	Preventive W.R. #42538	---	N/A	N/A	Welds ground.
756-101B Power Range Monitor Relay	Preventive W.R. #42561	---	N/A	N/A	Rebuilt relay.
2-1501-3A	Preventive W.R. #42567	---	N/A	N/A	Adjusted spring pack retainer nut.
FT-2-1551A LPCI Flow Trans.	Preventive W.R. #41924	---	N/A	N/A	Inspected - no repairs made.
FT-2-1551B LPCI Flow Trans.	Preventive W.R. #41925	---	N/A	N/A	Inspected - no repairs made.
LT-2-1641-5A Torus Level Trans.	Preventive W.R. #41926	---	N/A	N/A	Inspected - no repairs made.
PT-2-1625 D/W Pressure Trans.	Preventive W.R. #41928	---	N/A	N/A	Inspected - no repairs made.
Snubbers (2)	Corrective W.R. #41948	---	N/A	N/A	Installed flat washers.
SRM Shorting Links	Preventive W.R. #41977	---	N/A	N/A	Installed jumpers.
ATWS Rosemount Trans.	Preventive W.R. #41983	---	N/A	N/A	Replaced plugs.
2-305-129 HCU 14-15 High Water Alarm	Preventive W.R. #42024	---	N/A	N/A	Replaced level selector.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
2-1507B-U2 MOV	Preventive W.R. #42071	---	N/A	N/A	Inspected valve.
2-7505B MOV	Preventive W.R. #42073	---	N/A	N/A	Inspected valve.
2-7504B U2 MOV	Preventive W.R. #40275	---	N/A	N/A	Inspected valve.
Accumulator 14-51	Corrective W.R. #42082	---	N/A	N/A	Replaced accumulator.
U2 MOV 1501-21A	Preventive W.R. #42084	---	N/A	N/A	Inspection performed.
U2 MOV 1402-38B	Preventive W.R. #42085	---	N/A	N/A	Inspection performed.
U2 MOV 1501-32A	Preventive W.R. #42091	---	N/A	N/A	Inspection performed.
U2 MOV 1501-11A	Preventive W.R. #42092	---	N/A	N/A	Inspected - installed splices.
U2 MOV 1301-3	Preventive W.R. #42107	---	N/A	N/A	Inspection performed.
U2 MOV 1301-2	Preventive W.R. #42108	---	N/A	N/A	Inspection performed.
U2 MOV 1301-4	Preventive W.R. #42117	---	N/A	N/A	Inspected and installed splices.
U2 MOV 1001-1A	Preventive W.R. #42120	---	N/A	N/A	Inspection performed.
D2 Turbine Gen. 2-5600-6000	Preventive W.R. #35316	---	N/A	N/A	Overhauled generator.
2-202-7A Valve	Preventive W.R. #28735	---	N/A	N/A	Cleaned stems and tightened flats.
1601-32 and 33A-F	Preventive W.R. #30016	---	N/A	N/A	Replaced sealtite.
Pilot Sol. for AO2-220-45	Preventive W.R. #34709	---	N/A	N/A	Replaced solenoid valve.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
Scram Discharge Vol. Vents and Drain Air Sol. 2-0302-20B	Preventive W.R. #34913	---	N/A	N/A	Replaced solenoid.
2-2301 HPCI Turbine	Preventive W.R. #35762	---	N/A	N/A	Replacked and floated couplings.
2-203-3B Electro- matic Relief Valve	Preventive W.R. #35453	---	N/A	N/A	Removed blind flange and installed.
2-MO-202-5A Recirc. PP Discharge Valve	Preventive W.R. #35568	---	N/A	N/A	Checked for grease and tightness.
2-220-46 - Rx Head Vents	Preventive W.R. #36776	---	N/A	N/A	Replaced hose.
U2 ID MSIV	Preventive W.R. #36917	---	N/A	N/A	Replaced switches.
SRM Z1	Preventive W.R. #37015	---	N/A	N/A	Checked and found no problems.
LPRM 24-09A (APRM 3)	Preventive W.R. #37420	---	N/A	N/A	Completed DIS 700-21 and DIP 700-13.
Rx Head T/C's	Preventive W.R. #37541	---	N/A	N/A	Removed and installed T/C's.
HPCI Turbine 2-2302	Preventive W.R. #29237	---	N/A	N/A	Repaired control box cover - reinstalled conduit rebuilt valves.
305-117 Accumu- lator 26-07	Preventive W.R. #32606	---	N/A	N/A	Rebuilt valves.
Accumulator 22-47, 305-117	Preventive W.R. #32607	---	N/A	N/A	Rebuilt valves.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
Accumulator 26-47, 305-117	Preventive W.R. #32608	---	N/A	N/A	Rebuilt valves.
CRD 34-39	Preventive W.R. #33749	---	N/A	N/A	Rebuilt solenoids.
502-203-2A-0 MSIV Solenoid Valves	Preventive W.R. #34730	---	N/A	N/A	Replaced solenoids sealed conduit.
502-203-1A-0 MSIV Solenoid Valves	Preventive W.R. #34731	---	N/A	N/A	Repaired cable and conduit.
U2 "B" ATWS Invertor	Preventive W.R. #34837	---	N/A	N/A	Replaced inverter cooling fan.
Leak Test CRD's	Preventive W.R. #35466	---	N/A	N/A	Tested - found ok.
Auto Blowdown System HFA Relays	Preventive W.R. #36760 (Slave 1-8)	---	N/A	N/A	Rebuilt relays.
U2 HPCI MSL Ind. Light	Preventive W.R. #37382	---	N/A	N/A	Replaced indicator light limit switch.
Main Steam Isolating Control	Preventive W.R. #37677	---	N/A	N/A	Replaced coils and adjusted relays.
2-1601-20A	Preventive W.R. #38342	---	N/A	N/A	Tightened connection and put locktite on threads.
HPCI 2-2301 4 and 5 Valve	Preventive W.R. 38372	---	N/A	N/A	Jumpers removed.
Control Rod Drives	Corrective W.R. #38747	---	N/A	N/A	Removed and installed CRD's per procedure.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
Pressure Sensors	Preventive W.R. #39090	---	N/A	N/A	Tested - found no problem.
ECCS Relays	Preventive W.R. #39092	---	N/A	N/A	Installed blocks and removed wires.
LPRM 08-33B	Preventive W.R. #39256	---	N/A	N/A	No problems found.
Off-Gas Log Rad Monitor 1733A	Preventive W.R. #40488	---	N/A	N/A	Replaced and calibrated log rad monitor.
AO-2-2599-3A	Preventive W.R. #40532	---	N/A	N/A	Tightened-up loose fittings.
250VDC Battery Charger 2	Corrective W.R. #40602	---	N/A	N/A	Adjusted float and equalized voltage.
Snubbers (12)	Preventive W.R. #40655	---	N/A	N/A	Removed and replaced snubbers.
"F" Safety Valve 2-203-F	Corrective W.R. #40758	---	N/A	N/A	Replaced nipple.
Snubbers (8)	Preventive W.R. #40768	---	N/A	N/A	Replaced snubbers.
Snubbers (11)	Corrective W.R. #40769	---	N/A	N/A	Replaced snubbers.
Mechanical Snubbers (11)	Corrective W.R. #40849	---	N/A	N/A	Tested and replaced snubbers.
RPS Relay EPA 2A-2	Preventive W.R. #40915	---	N/A	N/A	Adjusted breaker.
2-203-3B Electromatic	Preventive W.R. #41003	---	N/A	N/A	Installed new sealtite, wires, lugs and splices.
CUB. 2302 Bus 23-23-1 Tie Breaker	Preventive W.R. #41179	---	N/A	N/A	Reconnected tie breaker.



DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
DWEDS Isolation Valve A0-2-2001-5	Corrective W.R. #41239	---	N/A	N/A	Replaced solenoid valve.
DWEDS Isolation Valve A0-2-2001-5 and 6	Corrective W.R. #41287	---	N/A	N/A	Replaced solenoid valve.
2-1403-104B Core Spray Relay	Corrective W.R. #41353	---	N/A	N/A	Adjusted relay contacts.
1430-106B Core Spray HFA Relay	Corrective W.R. #41354	---	N/A	N/A	Adjusted relay contacts.
U2 1502-18B MOV	Corrective W.R. #41388	---	N/A	N/A	Pulled breaker per procedure.
A0 8501-1A Torus Sample Valve 902-3	Preventive W.R. #41407	---	N/A	N/A	Tested - works correctly.
Refuel Grapple	Corrective W.R. #41413	---	N/A	N/A	Tested and replaced limits.
A0-2-9206A Valve	Corrective W.R. #41432	---	N/A	N/A	Replaced solenoid valve.
A0-2-9206-B	Corrective W.R. #41438	---	N/A	N/A	Replaced solenoid valve.
U2 MOV 1501-22A	Preventive W.R. #41504	---	N/A	N/A	Repaired sealrite
U2 AOV 2001-3	Preventive W.R. #41656	---	N/A	N/A	Changed grounded limit switch.
Core Spray Pressure Trans. PT-2-1460A	Preventive W.R. #41909	---	N/A	N/A	Inspected per procedure.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
LS-2-2351A HPCI Level Switch	Preventive W.R. #41911	---	N/A	N/A	Inspected switch.
LT-2-1641-5B Torus Level Trans.	Preventive W.R. #41927	---	N/A	N/A	Inspected - no repairs made.
PT-2-1641-6A D/W Pressure Trans.	Preventive W.R. #41929	---	N/A	N/A	Replaced plug and inspected.
PT-2-1641-6B D/W Pressure Trans.	Preventive W.R. #41930	---	N/A	N/A	Inspected and replaced plug.
PT-2-647A Rx Pressure Trans.	Preventive W.R. #41932	---	N/A	N/A	Inspected - no repairs made.
PT-2-647B Rx Pressure Trans.	Preventive W.R. #41933	---	N/A	N/A	Inspected - no repairs made.
PT-2-662 Rx Pressure Trans.	Preventive W.R. #41934	---	N/A	N/A	Inspected per procedure.
2-1501-27B U2 MOV	Preventive W.R. #42097	---	N/A	N/A	Performed E.Q. inspection.
U2 MOV-220-2	Preventive W.R. #42109	---	N/A	N/A	Performed E.Q. inspection.
U2 MOV-1301-1	Preventive W.R. #42118	---	N/A	N/A	Installed hoses, switches and harness.
Reactor Manual Control Timer	Preventive W.R. #42252	---	N/A	N/A	Lubricated and checked timing.
U2 5747 HPCI Room Cooler	Preventive W.R. #42290	---	N/A	N/A	Replaced motor.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
CRD EG	Preventive W.R. #42351	---	N/A	N/A	Installed drive and support steel.
D2 300 CRD L-4	Corrective W.R. #42381	---	N/A	N/A	Installed drive and support steel.
Control Blade	Preventive W.R. #42395	---	N/A	N/A	Freed drive installed GE blade.
U2 ROD E-1 Select Push- button	Preventive W.R. #42415	---	N/A	N/A	Replaced pushbutton switch.
CRD J-6	Corrective W.R. #42428	---	N/A	N/A	Replaced CRD, support steel and drive.
RWCU Aux. PP	Preventive W.R. #42464	---	N/A	N/A	Lifted leads.
U2 HPCI Root Valve PSH 2355	Corrective W.R. #42480	---	N/A	N/A	Repaired and replaced nipple.
1601-32E Torus to D/W Vacuum Breaker Piping	Corrective W.R. #42622	---	N/A	N/A	Removed arc strikes.
1601-33A Torus to D/W Vacuum Breaker Piping	Corrective W.R. #42623	---	N/A	N/A	Removed arc strikes.
Snubbers (4) "A" Main Steam Line	Preventive W.R. #42617	---	N/A	N/A	Replaced 4 snubbers.
2 "B" RPS MG Set	Preventive W.R. #42625	---	N/A	N/A	Took over loads from spare breaker.
1601-20A Pratt Vent Valve	Corrective W.R. #42635	---	N/A	N/A	Replaced one-half copper line.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
201601-32 and 12 Torus to D/W Vacuum Breakers	Preventive W.R. #42636	---	N/A	N/A	Performed procedure.
125VDC Battery Charger 2	Preventive W.R. #42688	---	N/A	N/A	Adjusted float and equalizer.
"A" Main Steam Line Support Clamp	Preventive W.R. #42705	---	N/A	N/A	Replaced clamp.
MOV 202-5A	Corrective W.R. #42845	---	N/A	N/A	Installed grease relief.
MOV 2-202-5B	Corrective W.R. #42846	---	N/A	N/A	Installed grease relief.
MOV 1301-1	Preventive W.R. #42847	---	N/A	N/A	Installed grease relief.
MOV 1301-4	Preventive W.R. #42848	---	N/A	N/A	Installed grease relief.
MOV 2-1001-1A	Corrective W.R. #42849	---	N/A	N/A	Installed grease relief.
MOV 1001-1B	Corrective W.R. #42850	---	N/A	N/A	Installed grease relief.
2-203-3D "D" Electromatic	Corrective W.R. #42915	---	N/A	N/A	Assembled coupling.
U2 Diesel Gen.	Preventive W.R. #42918	---	N/A	N/A	Inserted new blocking.
2-2302 HPCI Booster Pump	Corrective W.R. #42921	---	N/A	N/A	Installed gasket and sealtite.
2-1501-3B	Preventive W.R. #42971	---	N/A	N/A	Adjusted spring pack.
MO 2-1201-3 Valve	Corrective W.R. #42980	---	N/A	N/A	Replaced shaft and 3 gaskets.

DRESDEN UNIT 2

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
2-220-63A Valve	Preventive W.R. #42995	---	N/A	N/A	Adjusted packing.
2-202-7B Valve	Preventive W.R. #42996	---	N/A	N/A	Adjusted packing.
MO 2-1001-5B	Preventive W.R. #43008	---	N/A	N/A	Adjusted packing.
MO 2-1501-22B	Preventive W.R. #43009	---	N/A	N/A	Adjusted packing.
MO 2-1501-22A	Preventive W.R. #43010	---	N/A	N/A	Adjusted packing.
MO 2-1001-5A	Preventive W.R. #43011	---	N/A	N/A	Adjusted packing.
Valve 2-1301-505	Preventive W.R. #43012	---	N/A	N/A	Adjusted packing.
MO 2-1301-2	Preventive W.R. #43013	---	N/A	N/A	Adjusted packing.
AO-2-220-44 Valve	Preventive W.R. #43014	---	N/A	N/A	Adjusted packing.
MO 2-2301-4 Valve	Corrective W.R. #43015	---	N/A	N/A	Adjusted packing.
2-202-5A Valve	Preventive W.R. #43017	---	N/A	N/A	Adjusted packing.

DRESDEN UNIT 3

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
#3' Diesel Generator	Preventive W.R. #40262	---	N/A	N/A	Inspection performed.
LPRM 1C-16-49	Preventive W.R. #41231	---	N/A	N/A	Investigated - found no problem.
LPRM 32-25-D (GR-II)	Preventive W.R. #41249	---	N/A	N/A	Inspected - no problem.
LPRM 48-41C APRM #6	Preventive W.R. #41250	---	N/A	N/A	Inspected - all looks ok.
LPRM 16-49B	Preventive W.R. #41252	---	N/A	N/A	Inspected - found no problem.
LPRM 3B40-41 APRM 2	Preventive W.R. #41271	---	N/A	N/A	Inspected - all ok.
LPRM 5A40-25 APRM 3	Preventive W.R. #41272	---	N/A	N/A	Inspected - all ok.
LPRM 6A40-09 APRM 1	Preventive W.R. #41273	---	N/A	N/A	Inspected - all ok.
CRD 38-23	Corrective W.R. #41316	---	N/A	N/A	Tightened packing follower.
3-261-30A-D MSL Low Pressure Switch	Preventive W.R. #41318	---	N/A	N/A	Checked calibration.
SRM #22	Preventive W.R. #41320	---	N/A	N/A	Cleared and tightened ground connec- tion.
IRM #12	Preventive W.R. #41330	---	N/A	N/A	Found no problem.
PS-3261-30A-D Main Steam Line Low Pressure	Preventive W.R. #41339	---	N/A	N/A	Installed new switch.



DRESDEN UNIT 3

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
3-0305-126 CRD E-9 Scram Inlet Valve	Corrective W.R. #41368	---	N/A	N/A	Adjusted stem coupling.
RM3-750-1C SRM #22	Preventive W.R. #41399	---	N/A	N/A	Exercized discriminator pot.
Torus Level Alarm	Preventive W.R. #41592	---	N/A	N/A	Re-calibrated torus level instru- ments.
D3 HPCI A/C Cooling Water PP	Preventive W.R. #41714	---	N/A	N/A	Tightened packing gland.
LPRM 1D 16-49	Preventive W.R. #41759	---	N/A	N/A	Tested - looks good.
LPRM 4B 40-33	Preventive W.R. #41760	---	N/A	N/A	Tested - looks good.
LPRM 4D 40-33	Preventive W.R. #41785	---	N/A	N/A	Tested - looks good.
LPRM 3A 48-33 GRI	Preventive W.R. #41786	---	N/A	N/A	Checked - found no problem.
C-RPS Yarway	Preventive W.R. #41787	---	N/A	N/A	Tested - found no problem.
LPRM 6C 40-09	Preventive W.R. #41826	---	N/A	N/A	Tested - looks good.
3-2304-14C D3 HPCI Pipe Restraint	Corrective W.R. #41848	---	N/A	N/A	Re-installed and tightened nut.
LPRM 6D 32-09	Preventive W.R. #41890	---	N/A	N/A	Tested - found no problem.
ATWS Rosemount Trans.	Preventive W.R. #41981	---	N/A	N/A	Installed stainless steel plugs.
SRM #22	Preventive W.R. #41995	---	N/A	N/A	Checked - looks good.

DRESDEN UNIT 3

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
Accumulator 14-43	Corrective W.R. #42194	---	N/A	N/A	Changed accumulator.
RBM #8	Preventive W.R. #42302	---	N/A	N/A	Replaced I.C. G4 and Q1.
RBM #8	Preventive W.R. #42314	---	N/A	N/A	Re-set setpoint.
Rod Block Moni- tor #7	Preventive W.R. #42404	---	N/A	N/A	Performed DIS 700-8 Rev. 9.
LPRM Meter on 903-5 Panel for 16-17C	Preventive W.R. #42405	---	N/A	N/A	Replaced relay card.
D/W Equipment Hatch	Preventive W.R. #42581	---	N/A	N/A	Closed hatch.
D/W Equipment Hatch	Preventive W.R. #42582	---	N/A	N/A	Removed hatch.
APRM #4	Preventive W.R. #42616	---	N/A	N/A	Replaced relay.
3C CCSW Pump	Preventive W.R. #42670	---	N/A	N/A	Replaced FT-3-1542B.
3-1501-44C CCSW Pump	Preventive W.R. #42685	---	N/A	N/A	Overhauled pump.
APRM/RBM Flow Converters	Preventive W.R. #42739	---	N/A	N/A	Calibrated flow converters.
LPRM 2B 24-41	Preventive W.R. #42782	---	N/A	N/A	Tested - looks good.
LPRM 6C 32-09	Preventive W.R. #42793	---	N/A	N/A	Tested - looks good.
LPRM 3D 32-33	Preventive W.R. #42794	---	N/A	N/A	Tested - looks good.

DRESDEN UNIT 3

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
LPRM 3B 32-33	Preventive W.R. #43189	---	N/A	N/A	Tested - all ok.
M312/VH-17 Spring Hanger LPRM 5C 40-25	Preventive W.R. #43246	---	N/A	N/A	Burnt-off wisker - all ok.

DRESDEN UNIT 3

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
3-2301-7 HPCI Injection Test- able Check Valve	Corrective W.R. #42818	---	N/A	N/A	Added 4 rings of packing.
LPRM 08-25D	Preventive W.R. #40000	---	N/A	N/A	Checked and found ok.
LPRM 40-41C Ck. 3	Preventive W.R. #40469	---	N/A	N/A	Tested and checked - all looks good.
LPRM 16-33D	Preventive W.R. #40938	---	N/A	N/A	Disc. and tested - all ok.
PS-3-505C EHC Low Pressure Switch	Preventive W.R. #42001	---	N/A	N/A	Tested - looks good.
LPRM 16-49-D Channel #1	Preventive W.R. #42621	---	N/A	N/A	Changed connector on plant side cable.
LPRM 3C 48-41	Preventive W.R. #43048	---	N/A	N/A	Tested - found no problem.
LPRM 1C 16-49	Preventive W.R. #43049	---	N/A	N/A	Burned off wisker tested - no problem.
LPRM 4D 32-25	Preventive W.R. #43080	---	N/A	N/A	Burned off wisker tested - no problem.
LPRM 1B 32-49	Preventive W.R. #43081	---	N/A	N/A	Tested - all ok.
3B-1503 LPCI/ CCSW Heat Exchanger	Corrective W.R. #43100	---	N/A	N/A	Replaced top and bottom cover gasket.
3B-1503 LPCI/ CCSW Heat Exchanger	Corrective W.R. #43108	---	N/A	N/A	Jacked plate back to original position.
1501-44C Cont. Cooling Service Water PP.	Preventive W.R. #43147	---	N/A	N/A	Inspected - all ok.

DRESDEN UNIT 3SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
LPRM 3B 32-33	Preventive W.R. #43189	---	N/A	N/A	Tested - all ok.
M312/VH-17 Spring Hanger LPRM 5C 40-25	Preventive W.R. #43246	---	N/A	N/A	Burnt-off whisker - all ok.

DRESDEN UNIT 2/3

SAFETY RELATED MAINTENANCE - JUNE, 1985

EQUIPMENT	NATURE OF MAINTENANCE	LER OR OUTAGE NUMBER	MALFUNCTION		CORRECTIVE ACTION
			CAUSE	RESULT	
"B" SGBT Logic	Preventive W.R. #36722 (Slave 1-11)	---	N/A	N/A	Replaced coil and adjusted relay.
2-203-3B Electromatic Relief Valve	Corrective W.R. #35444	---	N/A	N/A	Reconditioned valve.
Standby Diesel Engine Air Start Motor	Corrective W.R. #41994	---	N/A	N/A	Rebuilt air start motor.
2/3-7503B Electric Heaters	Preventive W.R. #42175	---	N/A	N/A	Inspected heater.
Standby Gas Crosstie Damper	Preventive W.R. #43309	---	N/A	N/A	Everything ok.
SDV Level Switches	Preventive W.R. #43470	---	N/A	N/A	Replaced heater and sensor assembly.
2/3 Diesel Generator	Preventive W.R. #44175	---	N/A	N/A	Inspection performed.



## SUMMARY OF OPERATING EXPERIENCE

### UNIT TWO

JUNE, 1985

- 06-01 to 06-14      Unit 2 entered the month operating at a power level of 765 MWe and operated until 1105 hours of June 9th, when the unit was manually taken off-line because of 2B MG Set problems. At 1332 hours the Rx automatically scrambled because of Mode switch problems. While the unit was off-line, the main steam line snubbers were inspected. The Rx was made critical at 0450 of June 13th, and the unit was placed on-line at 1035 hours of June 14th.
- 06-14 to 06-21      The unit operated continuously, reaching a power level of 776 MWe, until 2113 hours of June 18th, when the unit was manually taken off-line because of EHC problems. On June 19th, at 0233 hours, the Rx automatically scrambled because of high level in the SDV. The Rx was made critical on June 20th at 1928 hours and the unit was placed in service at 0545 hours of June 21st.
- 06-21 to 06-30      The unit operated continuously the remainder of the month, reaching a power level of 680 MWe with a capacity factor of 59.57% and an availability of 75.55%.

SUMMARY OF OPERATING EXPERIENCE

UNIT THREE

JUNE, 1985

06-01 to 06-30      Unit 3 operated continuously the entire month of June, 1985 (with normal power reductions for weekend surveillances) reaching a power level of 803 MWe with a capacity factor of 89.21% and an availability of 100%.



**Commonwealth Edison**

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

July 1, 1985

DJS LTR: 85-721

Director, Office of Inspection  
and Enforcement  
United States Nuclear Regulatory  
Commission  
Washington, DC 20555

Attention: Document Control Desk

Dear Sir:

Enclosed, please find Dresden Station's operating data for last month. This information is supplied to your office per the instructions set forth in Regulatory Guide 1.16.

Sincerely,

D. J. Scott  
Station Manager  
Dresden Nuclear Power Station

DJS:DCM:hjb

Enclosure

cc: Region III, Regulatory Operations, U.S. NRC  
Chief, Division Nuclear Safety, State of IL  
U.S. NRC, Document Management Branch  
Nuclear Licensing Administrator  
Nuclear Fuel Services Manager  
Nuc. Sta. Div. Vice Pres.  
Manager, Tech. Nuc. Sta.  
Tech. Staff A.E.  
On-Site NRC Inspector  
Sta. Nuc. Eng. Dept.  
Comptroller's Office  
PIP Coordinator  
INPO Records Center  
File/NRC Op. Data  
File/Numerical

IE24  
11