

APPENDIX B
Deviation
NOTICE OF ~~VIOLATION~~

Boston Edison Company
Pilgrim Nuclear Power Station

Docket No. 50-293
License No. DPR-35

As a result of the inspection conducted on May 20-24, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following deviation was identified:

IE Bulletin 80-10 requires, in part, that: 1) a review of facility design and operation be performed to identify systems that are considered as nonradioactive, but could possibly become contaminated through interfaces with contaminated systems; 2) a routine sampling/analysis or monitoring program be established for these systems in order to promptly identify any contaminating events which could lead to unmonitored, uncontrolled, liquid or gaseous releases to the environment, including releases to on-site leaching fields and; 3) the specifics of these reviews be documented and made available to the NRC for review during future on-site inspection efforts. In particular, special consideration was to be given to the instrument air system and the sanitary waste system. The licensee's response to this Bulletin indicated that the above was implemented.

Contrary to the above, as of May 24, 1985: 1) the instrument air system and sanitary waste system had not been reviewed to determine if these systems could become contaminated through interfaces with contaminated systems; 2) no routine sampling/analysis or monitoring program (as appropriate) was established in order to promptly identify any contaminating events which could lead to unmonitored/uncontrolled releases from these systems; and 3) no specifics relative to the above were documented and made available to the NRC.

Pursuant to the provisions of 10 CFR 2.201, Boston Edison Company is hereby requested to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further deviations and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8507220385 850716
PDR ADOCK 05000293
Q PDR

APPENDIX B
Deviation
NOTICE OF VIOLATION

Boston Edison Company
Pilgrim Nuclear Power Station

Docket No. 50-293
License No. DPR-35

As a result of the inspection conducted on May 20-24, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following deviation was identified:

IE Bulletin 80-10 requires, in part, that: 1) a review of facility design and operation be performed to identify systems that are considered as nonradioactive, but could possibly become contaminated through interfaces with contaminated systems; 2) a routine sampling/analysis or monitoring program be established for these systems in order to promptly identify any contaminating events which could lead to unmonitored, uncontrolled, liquid or gaseous releases to the environment, including releases to on-site leaching fields and; 3) the specifics of these reviews be documented and made available to the NRC for review during future on-site inspection efforts. In particular, special consideration was to be given to the instrument air system and the sanitary waste system. The licensee's response to this Bulletin indicated that the above was implemented.

Contrary to the above, as of May 24, 1985: 1) the instrument air system and sanitary waste system had not been reviewed to determine if these systems could become contaminated through interfaces with contaminated systems; 2) no routine sampling/analysis or monitoring program (as appropriate) was established in order to promptly identify any contaminating events which could lead to unmonitored/uncontrolled releases from these systems; and 3) no specifics relative to the above were documented and made available to the NRC.

Pursuant to the provisions of 10 CFR 2.201, Boston Edison Company is hereby requested to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further deviations and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.