



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

September 14, 1983

Mr. J.C. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,
the following reports are submitted:

RO 83-079/03L-0
RO 83-080/03L-0

Sincerely,

W.G. Smith, Jr.
Plant Manager

/cbm

cc: J.E. Dolan
M.P. Alexich
R.F. Kroeger
H. Brugger
E. Swanson/N. DuBry RO:III
R.C. Callen MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee
INPO
PNRRC
J.F. Stietzel
E.L. Townley
Dir., IE (30 copies)
Dir., MIPC (3 copies)

SEP 19 1983

1E22
1/1
83 RETROFIT

8506100075 830914
PDR ADOCK 05000316
S PDR

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

011 | M | I | D | C | C | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | | 5

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CONIT LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CONT
011
REPORT SOURCE 1 L 6 0 5 0 0 0 0 3 1 1 6 7 0 18 1 1 7 8 3 3 0 9 1 1 4 8 13 1 9
60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
DOCKET NUMBER EVENT DATE REPORT DATE
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

| | | | | | | | | | | | |
|---|--|---------------------------|--|---|--|------------------------------------|--|--------------------------------|--|-------------------------------|--|
| SYSTEM CODE A B (11) | | CAUSE CODE E (12) | | CAUSE SUBCODE A (13) | | COMPONENT CODE I N S T R U (14) | | COMP SUBCODE E (15) | | VALVE SUBCODE Z (16) | |
| EVENT YEAR 8 3 (17) | | SHUTDOWN METHOD — (23) | | SEQUENTIAL REPORT NO. 0 1 7 1 9 (24) | | OCCURRENCE CODE 0 1 3 (25) | | REPORT TYPE L (30) | | REVISION NO. 0 (32) | |
| ACTION TAKEN A (33) | | FUTURE ACTION Z (34) | | EFFECT ON PLANT Z (35) | | HOURS 0 0 0 0 0 (36) | | ATTACHMENT SUBMITTED N (41) | | PRIME COMP SUPPLIER N (43) | |
| CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) | | | | | | | | | | | |

| | | | | | | | | | | | | |
|-----------------|----|---------|----|----|--------------|----|----|----------------------|----|----|-----------------------|----|
| 113 | | | | | | | | | | | | |
| 114 | | | | | | | | | | | | |
| 8 | 9 | | | | | | | | | | | |
| FACILITY STATUS | | % POWER | | | OTHER STATUS | | | METHOD OF DISCOVERY | | | DISCOVERY DESCRIPTION | |
| 115 | E | 1 | 0 | 1 | 0 | NA | B | OPERATOR OBSERVATION | | | | |
| 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 |
| ACTIVITY | | CONTENT | | | | | | | | | | |

| PERSONNEL EXPOSURES | | | | 44 | 45 | 81 |
|---------------------|------|-------------|------|----|----|----|
| NUMBER | TYPE | DESCRIPTION | (39) | | | |
| 111 | 000 | (17) Z (38) | NA | | | |

| PERSONNEL INJURIES | | DESCRIPTION |
|--------------------|---|-------------|
| 0 | 0 | 0 |

NA

| 10 | 11 | 12 | 13 |
|-------------------------------|-------------|------|----|
| LOSS OF OR DAMAGE TO FACILITY | | | |
| TYPE | DESCRIPTION | (43) | |
| Z | (47) | | |
| NA | | | |

Dup 4309.230208

10
PUBLICITY
ISSUED DESCRIPTION (45)
2101 N 44
NA
NRC USE ONLY

NRC USE ONLY
 68 69
 PHONE 616-465-5901