

SAFETY INSPECTION

Page 1 of 2

1. LICENSEE *STS Acquisition Company*
3340 Ranger Road
Lansing, MI 48906

2. REGIONAL OFFICE

REGION III
U S NUCLEAR REGULATORY COMMISSION
801 WARRENVILLE ROAD
LISLE IL 60532-4351

3. DOCKET NUMBER(S)

4. LICENSE NUMBER(S)

5. DATE OF INSPECTION

030-18485

21-24330-0

September 17-18, 1996

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- ☒ 1. Within the scope of this inspection, ^{*Cited*} no violations were observed.
- ☒ 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- ☐ 3. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a **NOTICE OF VIOLATION**, which is required to be posted in accordance with 10 CFR 19.11.

- ☐ A. _____ was not properly posted to indicate the presence of a _____ 10 CFR 20.203(b),(c),(d),(e) or 34.42.
- ☐ B. _____ of sealed sources were not performed at the proper frequencies. 10 CFR _____ or License Condition Number _____.
- ☐ C. Records of _____ were not properly maintained. 10 CFR _____ or License Condition Number _____.
- ☐ D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
- ☐ E. Reports or notification of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____.
- ☐ F. _____

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE -- LICENSEE

DATE

SIGNATURE -- NRC INSPECTOR

DATE

9611250169 960918
PDR ADOCK 03018485
C PDR

Amelia KAK

9/18/96

IE07

SAFETY INSPECTION

Page 2 of 2

1. LICENSEE

STS Acquisition Company

2. REGIONAL OFFICE

3340 Ranger Road
Lansing, MI 48906REGION III
U S NUCLEAR REGULATORY COMMISSION
801 WARRENVILLE ROAD
LISLE IL 60532-4351

3. DOCKET NUMBER(S)

030-18485

4. LICENSE NUMBER(S)

21-24330-01

5. DATE OF INSPECTION

September 17-18, 1996

3. (Continued)

☐ G.☐ H.☐ I.☒ 4. The violations listed below are not being cited because they were self-identified, and corrective action was or is being taken, and the remaining criteria in 10 CFR 2, App. C, to exercise discretion were satisfied.☒ A.

License condition 12(A) requires testing sealed sources for leakage at intervals not to exceed 6 months. However, from 8/1/85 to 3/27/96, from 6/1/95 to 11/14/95 and for several other crises, the license holder tested sealed sources at seven month intervals.

☐ B.☐ C.