




**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 409 838-6631

September 16, 1985  
RBG- 22,121  
File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



Dear Mr. Martin:

River Bend Station - Unit 1  
Docket No. 50-458  
Interim Report/DR-314

An interim or final status report on DR-314 concerning leakage of the fluid Fyrquel from pump seals to the pump drive motor in Borg-Warner electrohydraulic operators for Copes-Vulcan modulating valves will be provided by October 16, 1985.

Sincerely,

J. E. Booker  
Manager-Engineering,  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

*for PJD*  
JEB/PJD/lp

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

NRC Resident Inspector-Site

8509250365 850916  
PDR ADOCK 05000458  
S PDR

85-854

12-27  
1/0