

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
DIABLO CANYON, UNIT 1DOCKET NUMBER (2)
0 5 0 0 0 2 7 5 1 OF 0 1TITLE (4)
CONDITION NOT PERMITTED BY TECHNICAL SPECIFICATIONS

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0	5	0	5	8	5	0	1	8	0 0 0 7 0 9 8 5		0 5 0 0 0

OPERATING MODE (9)	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																								
1	<table border="1"><tr><td>20.402(b)</td><td>20.405(c)</td><td>50.73(a)(2)(iv)</td><td>73.71(b)</td></tr><tr><td>20.405(a)(1)(i)</td><td>50.36(c)(1)</td><td>50.73(a)(2)(v)</td><td>73.71(e)</td></tr><tr><td>20.405(a)(1)(ii)</td><td>50.36(c)(2)</td><td>50.73(a)(2)(vi)</td><td>OTHER (Specify in Abstract below and in Text, NRC Form 365A)</td></tr><tr><td>20.405(a)(1)(iii)</td><td>X 50.73(a)(2)(i)</td><td>50.73(a)(2)(vii)(A)</td><td></td></tr><tr><td>20.405(a)(1)(iv)</td><td>50.73(a)(2)(ii)</td><td>50.73(a)(2)(vii)(B)</td><td></td></tr><tr><td>20.405(a)(1)(v)</td><td>50.73(a)(2)(iii)</td><td>50.73(a)(2)(ix)</td><td></td></tr></table>	20.402(b)	20.405(c)	50.73(a)(2)(iv)	73.71(b)	20.405(a)(1)(i)	50.36(c)(1)	50.73(a)(2)(v)	73.71(e)	20.405(a)(1)(ii)	50.36(c)(2)	50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 365A)	20.405(a)(1)(iii)	X 50.73(a)(2)(i)	50.73(a)(2)(vii)(A)		20.405(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(vii)(B)		20.405(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(ix)	
20.402(b)	20.405(c)	50.73(a)(2)(iv)	73.71(b)																						
20.405(a)(1)(i)	50.36(c)(1)	50.73(a)(2)(v)	73.71(e)																						
20.405(a)(1)(ii)	50.36(c)(2)	50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 365A)																						
20.405(a)(1)(iii)	X 50.73(a)(2)(i)	50.73(a)(2)(vii)(A)																							
20.405(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(vii)(B)																							
20.405(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(ix)																							

LICENSEE CONTACT FOR THIS LER (12)
NAME
DAVID P. SISK, REGULATORY COMPLIANCE ENGINEERTELEPHONE NUMBER
AREA CODE
8 0 5 5 9 5 - 7 3 5 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	

SUPPLEMENTAL REPORT EXPECTED (14)
☐ YES (If yes, complete EXPECTED SUBMISSION DATE)
☒ NOEXPECTED SUBMISSION DATE (15)
MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At approximately 1000 PDT, May 5, 1985, with the unit in Mode 1 (Power Operation), the Limiting Conditions For Operation (LCO) time requirement was exceeded for Technical Specification (TS) 3.3.3.6, Action b. Test leads were left connected to the Reactor Coolant Outlet Temperature Monitors after completion of Surveillance Test Procedure (STP) R-27, "Incore Thermocouples and RCS RTD Cross Calibration."

The connected leads were discovered on May 10, 1985 and removed immediately. On June 11, 1985, after an extensive study, this event was determined to be reportable. This event was caused by a lack of communication, in that plant personnel performing the STP went off shift without indicating to their relief that the test leads were still connected and the oncoming shift did not visually confirm that the leads had been removed in accordance with STP R-27.

An immediate corrective action was completed on the same day of discovery, May 10, 1985, by removing the connected leads.

To prevent recurrence, all concerned personnel have received additional training on the importance of completing STPs, and FSAR electrical separation criteria.

8507240167 850709
PDR ADOCK 05000275
S PDRIE 22
11

PACIFIC GAS AND ELECTRIC COMPANY

PG&E

77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 781-4211 • TWX 910-372-6587

JAMES D. SHIFFER
VICE PRESIDENT
NUCLEAR POWER GENERATION

July 9, 1985

PGandE Letter No.: DCL-85-236

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Re: Docket No. 50-275, OL-DPR-80
Diablo Canyon Unit 1
Licensee Event Report 85-018-00
Condition Not Permitted by Technical Specifications


Gentlemen:

Pursuant to 10 CFR 50.73(a)(2)(i)(B), PGandE is submitting the enclosed Licensee Event Report concerning a condition not permitted by Technical Specifications.

This event has in no way affected the public's health and safety.

Kindly acknowledge receipt of this material on the enclosed copy of this letter and return it in the enclosed addressed envelope.

Sincerely,


J. D. Shiffer

Enclosure

cc: J. B. Martin
Service List

IE22
11