



VECELLIO & GROGAN INC.

RECEIVED

18 1130
JUN 6 PM 1 23

June 2, 1980

Nuclear Regulatory Commission
Division of Fuel Cycle and Material Safety
Material Licensing Branch
Washington, D.C. 20555

U.S. NUCLEAR REG.
NMS

Attention: Leah Tremper

RE: Mail Control No. 03536

Gentlemen:

Enclosed is the additional information needed to support our application for a by product material license. The information is as follows:

Items 8 and 9

The following personnel, training and experience included, will perform or directly supervise the operation of the nuclear gauges:

Gary Adkins	- Troxler Training Program and the West Virginia Department of Highways Nuclear Compaction School.
Bruce Clark	- Troxler Training Program and the West Virginia Department of Highways Nuclear Compaction School.
Ronald Hodges	- Troxler Training Program and the West Virginia Department of Highways Nuclear Compaction School.
Mike Lively	- Troxler Training Program and the West Virginia Department of Highways Nuclear Compaction School.
David Mathias	- Troxler Training Program and the West Virginia Department of Highways Nuclear Compaction School.
Ray Nash	- Troxler Training Program and the West Virginia Department of Highways Nuclear Compaction School.
Emmitt Pinnell	- Troxler Training Program and the West Virginia Department of Highways Nuclear Compaction School.

Item 13

The permanent storage area for our nuclear gauges is located within a concrete vault (sketch included with application) at our main office situated approximately one-half (1/2) mile south of Beckley, West Virginia on Route 16.

COPIES SENT TO OFF. OF
INSPECTION AND ENFORCEMENT



VECELLIO & GROGAN INC.

1190

Item 14(a)

The nuclear gauges, when being transported will have their source rod locks in place and the gauge itself placed in its container. The container will be secured, to prevent movement, in an area as far removed from the driver and passengers as possible.

Items 14(e)

If the gauge becomes damaged or inoperative, which requires dismantling, the gauge will be immediately returned to the manufacturer for repair.

Sincerely,

VECELLIO & GROGAN, INC.

Dave Mathias,
Engineer

DM:ndw

Enclosure