

NMSS:JEW
Control No. 460611

MAY 23 1985

B&B Perforators
ATTN: Craig E. Bullard
Radiation Protection Officer
P. O. Box 787
Upton, Wyoming 82730

Gentlemen:

This is in reference to your request for a byproduct material license in the name of B&B Perforators. In order for us to complete our review of your request, please supply the following:

1. Inspection and maintenance should be conducted, at intervals not to exceed 6 months, on source holders, logging tools, source handling tools, storage containers, and transport containers to assure proper labeling and the device's physical condition. Should any damage be revealed, the device should be removed from service until repairs have been made. Records of inspection and maintenance should be maintained for a period of 2 years for inspection by the NRC. Amend your procedures for conducting inspection and maintenance of source holders, logging tools, source handling tools, storage containers, and transport containers.
2. The following documents and records should be available at temporary job sites:
 - a. Operating and emergency procedures.
 - b. Survey records for the period of operation at the temporary job site.
 - c. Evidence of current calibration for the radiation survey instruments in use at the temporary job sites.
 - d. When operating in an Agreement State under reciprocity, a copy of your NRC license.

It is not necessary to submit copies of documents you will have available at all temporary job sites. You need only state that you plan to have these documents available for NRC/Agreement State inspection, just restate the documents you plan to have available at each temporary job site.

NMSS
JEWitten;df
5/21/85

C:NMSS
RJEverett
5/21/85

8507240333 850625
REG4 LIC30
49-23177-01 PDR

3. All the procedures in 10 CFR 30.56 (a-d) should be addressed in your application. You should amend and resubmit for NRC staff review you application to address these changes.

We will continue our review of your application upon receipt of this information. Please reply in duplicate and refer to Control No. 460611.

Sincerely,

Original Signed By
Jack E. Whitten
Jack E. Whitten
Nuclear Materials Safety Section




UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

BETWEEN: William O. Miller, Chief
License Fee Management Branch
Office of Administration

R. J. Everett, Chief
Material Radiation Protection Section, TPB,
DV&TP, RIV



LICENSEE FEE TRANSMITTAL

A. REGION IV

1. APPLICATION ATTACHED

Applicant/Licensee:

B & B Perf.

Application Dated:

April 5, 1985

Control No.:

460611

License No.:

(030-28656)

2. FEE ATTACHED

Amount:

\$700-

Check No.:

168

3. COMMENTS

Signed

Laura Hurley

Date

April 30, 1985

B. LICENSEE FEE MANAGEMENT BRANCH

1. Fee Category and Amount:

No info 5A \$700

2. Correct Fee Paid. Application may be processed for:

Amendment _____

Renewal _____

License ✓

Signed

Frances Brown

Date

5/2/85

90 8/3