

VIRGINIA ELECTRIC AND POWER COMPANY

RICHMOND, VIRGINIA 23261

85 SEP 18 AM 11:39

W. L. STEWART
VICE PRESIDENT
NUCLEAR OPERATIONS

September 12, 1985

Dr. J. Nelson Grace
Regional Administrator
Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street
Suite 2900
Atlanta, Georgia 30323

Serial No. 85-624
NO/ALM:acm
Docket Nos. 50-338
50-339
License Nos. NPF-4
NPF-7

Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY
NORTH ANNA POWER STATION
NOTIFICATION OF DELETION OF SECURITY POST

In our response (Serial No. 383A, August 1, 1984) to your Notice of Violation (Inspection Report Nos. 50-338/84-18 and 50-339/84-18 dated June 11, 1984) we stated that a security post would be established at the entrance turnstiles as one of several corrective steps taken to improve the access control process to the plant. These steps have been effective in heightening the awareness of the access control officers, improving the badge issuing procedure, enhancing the legibility of the names and badge numbers on the badges, and establishing the full cooperation of all individuals requesting their badges to ensure that they have been issued the correct badge.

Statistical evidence has been assembled (Attachment 1) to verify that the corrective measures taken are effective. Attachment 1 indicates that since the establishment of the corrective steps that only 1 badge out of 327,213 issued have been detected by the security officer at the turnstiles as being incorrectly issued. Accuracy in the issuing process is ensured by the Access Control Officer, who first requests the individual's badge number, then verifies the number and compares the identity of the individual to the badge photograph, and finally requests the name of the individual to verify with the badge prior to issuance. Given the noted improvement in badge issuance we conclude that eliminating the security post at the turnstiles does not degrade access control

8509260295 850912
PDR ADOCK 05000338
G PDR

requirements. We believe that the manpower required to staff this 24 hour post (approximately 5 full time security officers) can now be more effectively assigned. Therefore, effective October 1, 1985, we intend to eliminate the Security Post at the entrance turnstiles. This action is consistent with direction provided by your Staff as documented in Inspection Report Nos. 50-338/85-23 and 50-339/84-23 dated August 15, 1985.

If additional information is required, please let us know.

Very truly yours,



W. L. Stewart

cc: Mr. Roger D. Walker, Director
Division of Project and Resident Programs

Mr. Edward J. Butcher, Acting Chief
Operating Reactors Branch No. 3
Division of Licensing

Mr. M. W. Branch
NRC Resident Inspector
North Anna Power Station

NORTH ANNA - SECURITY ACCESS CONTROL BUILDING

The following is the number of photo I.D. badges issued, monthly, during the period between September 1984 to July 1985.

| | DAILY | MONTHLY |
|----------------|--------|---------|
| | ----- | ----- |
| 1984 September | 2,700 | 81,000 |
| October | 2,653 | 82,243 |
| November | 583 | 17,490 |
| December | 526 | 16,322 |
| 1985 January | 567 | 17,567 |
| February | 551 | 15,424 |
| March | 498 | 15,428 |
| April | 708 | 21,256 |
| May | 668 | 20,722 |
| June | 650 | 29,495 |
| July | 654 | 20,266 |
| | ----- | ----- |
| Totals | 10,758 | 327,213 |

| | |
|---------------------------------------|-----|
| Average number of badges issued daily | 978 |
|---------------------------------------|-----|

| | |
|---|---|
| Number of badges issued incorrectly and detected by Security Officer at the Turnstile | 1 |
|---|---|

| | |
|---|------------|
| Percentage of wrong badges issued since this post was established | 0.0003056% |
|---|------------|