

DMB COPY

JUL 17 1985

Calumet Testing Services, Inc.
ATTN: Mr. Robert Vidimos
President
1945 N. Griffith Boulevard
Griffith, Indiana 46319

License No. 13-16347-01

Gentlemen:

This refers to the special safety inspection conducted by Mr. G. L. Shear of this office on June 21, 25 and 29, and July 16, 1985, of activities authorized by NRC Byproduct Material License No. 13-16347-01 and to the discussion of our findings with you on June 25, 1985. The results of the inspection were discussed on July 8, 1985, during an enforcement conference in the Region III office between you and me and others of the NRC staff.

The inspection was conducted in response to a reported extremity overexposure and was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection certain of your activities appeared to be in noncompliance with NRC requirements. You will be notified by separate correspondence of our decision regarding enforcement actions based on the findings of this inspection. No written response is required until you are notified of the proposed enforcement action.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

8508010489 850717
REG3 LIC30
13-16347-01 PDR

J. A. Hind
J. A. Hind, Director
Division of Radiation Safety
and Safeguards

Enclosure: Inspection Report
No. 030-10856/85002(DRSS)

cc w/enclosure:
DMB/Document Control Desk (RIDS)

bcc: J. Axelrad, IE

yes
RIII
US for
Shear/d
07/11/85

yes
RIII
DS
Sreniawski
7/16

RIII
USA
Axelson
7/16/85

2 copies yes
RIII
WKS
Schultz
7-17-85

RIII
Hand
Hind
7/17/85

IE07
11