

DMB COPY

JUL 15 1985

Diagnostic Services, Inc.
ATTN: James L. Purdie, M.D.
308 SW. 15th Street
Forest Lake, MN 55025

License No. 22-14883-02

36-13718

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. L. Lynch of this office on July 2, 1985, of activities authorized by NRC Byproduct Material License No. 22-14883-02 and to the discussion of our findings with you, Mr. M. Kach and Ms. P. Dellwo at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.


During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

Item of noncompliance No. 2 is a repeat item. In your response to this item of noncompliance, please describe why your proposed corrective action is expected to be more successful in preventing future or similar noncompliance than the corrective action specified in your December 23, 1981 letter.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.


Sincerely,



D. G. Wiedeman, Chief
Nuclear Materials Safety
Section 1

Enclosure: Appendix,
Notice of Violation

cc w/enclosure:
DMB/Document Control Desk (RIDS)

8508010573 850715
REQ3 LIC30
22-14883-02 PDR

RIII 
Lynch/ld
07/15/85

RIII 
Wiedeman
7/15/85

IE07
111