

ENCLOSURE 1

NOTICE OF VIOLATION

Carolina Power and Light Company
Brunswick 1 and 2

Docket Nos. 50-325 and 50-324
License Nos. DPR-71 and DPR-62

The following violation was identified during an inspection conducted on June 1-30, 1985. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.8.1.a requires the licensee to establish procedures recommended in Appendix "A" of Regulatory Guide 1.33, November 1972. Item H.2 of the guide specifies that procedures are required for each surveillance test, inspection and calibration listed in the Technical Specification. Technical Specification Surveillance requirement 4.9.6.d requires demonstration of the slack cable cutoff when the load is less than 50 plus-minus 5 pounds for the mast fuel gripper.

Contrary to the above, the licensee did not establish an adequate procedure for Technical Specification Surveillance 4.9.6.d in that Periodic Test PT-18.1 did not demonstrate operation of the slack cable cutoff when the load was less than 50 plus-minus 25 pounds for the mast fuel gripper.

This is a Severity Level V violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: JUL 12 1985

8508010793 850712
PDR ADOCK 05000324
G PDR