

UMB



TOLEDO  
EDISON

**JOE WILLIAMS, JR.**  
Senior Vice President—Nuclear  
(419) 249-2300  
(419) 249-5223

PRIORITY ROUTING

First	Second
RA	HC
MA	PC
MS	SL
WSS	OL
WMA	OC
	GO

FILE *low*

orig + 1

Enclosed is Revision 9 of the Safety-Related Piping System Support and Hanger Discrepancies Summary Report for the Davis-Besse Nuclear Power Station Unit No. 1. Toledo Edison is updating this report weekly and submitting it to your office to keep your Staff notified of any new discrepancies, regardless of significance, which are identified on safety-related piping system hangers or supports.

J Williams Sr / ym

cc: DB-1 NRC Resident Inspector  
D. Danielson, NRC Region III  
I. N. Jackiw, NRC Region III

8510010086 850920  
PDR ADCK 05000346  
P PDR

SEP 23 1985

THE TOLEDO EDISON COMPANY    EDISON PLAZA    300 MADISON AVENUE    TOLEDO, OHIO 43652

101