

JUL 1 6 1985

Docket No. 50-409

Dairyland Power Cooperative
ATTN: Mr. F. W. Linder
General Manager
2615 East Avenue - South
La Crosse, WI 54601

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. Snell and others of this office on June 24-26, 1985 of activities at the La Crosse Boiling Water Reactor authorized by NRC Operating Licenses No. DPR-45 and to the discussion of our findings with Messrs. J. Parkyn, T. Steele and others of your staff at the conclusion of the inspection.


The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

However, weaknesses were identified which will need corrective action by your staff. These weaknesses are summarized in the attached Appendix to this letter. As required by 10 CFR Part 50, Appendix E, IV.F, any weaknesses that are identified must be corrected.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,


C. J. Paperiello, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosures:

1. Appendix, Exercise Weaknesses
2. Inspection Report
No. 50-409/85008(DRSS)

IEBS
11

See Attached List For Distribution

8508020008 850716
PDR ADOCK 05000409
Q PDR

Dairyland Power Cooperative

2

JUL 1 6 1985

Distribution

cc w/enclosures:

J. Parkyn, Plant Superintendent
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
John J. Duffy, Chief
Boiler Section
Ness Flores, Chairperson
Wisconsin Public Service
Commission
Spark Burmaster, Coulee
Region Energy Coalition
W. Weaver, FEMA, Region V
D. Matthews, EPB, OIE

✓ RIII
WSnell
Snell/pg
07/11/85

✓ RIII
WRW
Williamsen

✓ RIII
JOP for
Phillips

RIII
Boyd

RIII
Papiello

APPENDIX

EXERCISE WEAKNESSES

1. Initial notifications to the offsite agencies for the Alert and Site Area Emergency classifications took longer than the 15 minutes specified in 10 CFR Part 50, Appendix E, IV.D.3. (Open Item No. 409/85008-01) (Section 4.a)
2. The content of the initial notification to the offsite agencies for the Site Area Emergency did not state whether a release was in progress as required by the LACBWR Emergency Plan. (Open Item No. 409/85008-02) (Section 4.a)