

8900 Fairbanks North Houston Road
P O Box 40066
Houston, Texas 77240
713 466 7581

August 24, 1984

84 AUG 27 P 3:07

Mr. Joseph C. Wang
Material Licensing Branch
Division of Fuel Cycle & Material Safety
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

SUBJECT: Renewal of Material License Number 42-13553-02
My transmittal of May 17, 1984

Dear Mr. Wang:

Since my previous referenced transmittal for renewal of this license, CBI has had additional personnel changes due to layoffs and transfers. There have also been DOT rule changes.

These have resulted in additional changes to the CBI Isotope Safety Program in Sections 3, 8, 15 and 16.

Enclosed are two (2) copies of the corrected index page and all pages of Sections 3, 8, 15 and 16. The changes in these sections consists of:

1. Section 3 - Personnel and address changes due to recent layoffs, transfers, etc.
2. Section 8 - Clarified the term "shipping package" and modified Form HO 85 and changed its designation to WL 85. Section now contains nine pages in lieu of seven.
3. Section 15 - Clarified paragraph 3.2.1 and changed all references for HO 85 to WL 85.
4. Section 16 - Revised forms WL 189 and WL 287A as well as WL 85. This, in turn, necessitated a revision of the samples shown on pages 7, 8, 14 and 17 through 24 (previously through page 22). Due to DOT rule changes, we also made some revisions to the IATA samples on pages 25 through 36 (previously pages 23 through 30).

Please insert these sections in your two (2) existing copies of the CBI Program in lieu of the existing sections.

8507170746 850528
REQ4 LIC30
42-13553-02 PDR


Chicago Bridge & Iron Company

Mr. Joseph Wang
August 24, 1984
PAGE 2

We would appreciate it if you could include these additional changes as part of our existing pending license renewal request.

Should you wish to contact me, my telephone number is (713) 466-7581, Ext. 271.

Sincerely yours,



Charles N. Sherlock
Radiation Safety Officer
Houston Corporate Welding

CNS/ab
Enclosures