

July 5, 1985

30-19024
45-19643-01

To Whom it May Concern,

I Marvin G. Dalton, owner operator of Coal Bore Hole Surveys Inc., do admitt to the alleged violations made by the inspection on March 21,1985.

The reasons for my violations are that I did not have a radation safety officer at that time, and did not have all of the required paper work, and was not familiar with all the regulations.

Corrective steps are being taken to correct all of these violations. Such as having the survey instrument calibrated, running the leak tests, correcting the film badge problem that I had. Also drawing up shipping papers for transportation.

These steps are being taken to avoid any further violations and the sources are not being used at this time until everything is corrected. The date for full compliance should be around the last week of August. Coal Bore Hole Surveys is in the process of having the building storage boxes made for the sources while they are not in use. Thank you for your kindness and understanding in the past. Loosing my brother,who was the safety officer left me blank on a lot of things concerning rules and regulations. In no way did I intentionally violate the rules.

THANK-YOU

MARVIN G. DALTON
Marvin G. Dalton
OWNER-OPERATOR

COAL BORE HOLE
SURVEYS INC.

8508020417 850705
NMSS LIC30
45-19643-01
PDR

IE 07 1/0