

Commonwealth Edison Company
Byron Generating Station
4450 North German Church Road
Byron, IL 61010-9794
Tel 815-234-5441



December 17, 1996

LTR: BYRON-96-5197

FILE: 3.11.0530

Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

ATTENTION: Document Control Desk

SUBJECT: ComEd Byron Station Unit 2 Steam Generator Eddy Current
Examination During B2F17 & B2R06 - 90 Day Summary Report

Byron Nuclear Power Station, Unit 2
Facility Operating License NPF-66
NRC Docket No. 50-455

Please find attached a report for the Byron Unit 2 Steam Generator examination performed during Cycle 6 forced (B2F17) and refueling outage (B2R06) during August 1996. This report is being submitted in compliance with the requirements of Mandatory Appendix IV of Section XI of the ASME Boiler and Pressure Vessel Code, 1983 Edition through Summer 1983 Addenda in accordance with Byron Technical Specification 4.0.5.

If there are any additional questions, please contact Marcia Lesniak, Nuclear Licensing Administrator at (630)663-6484.

Sincerely,

A handwritten signature in dark ink, appearing to read 'David B. Wozniak', is written over the typed name.

David B. Wozniak
Site Engineering Manager
Byron Nuclear Power Station

DBW/cb

Attachment

cc: A. B. Beach, NRC Regional Administrator, RIII
G. F. Dick, Jr., Byron Project Manager - NRR
S. D. Burgess, Senior Resident Inspector, Byron
Office of Nuclear Safety - IDNS

9612270082 961217
PDR ADQCK 05000455
PDR

A Unicom Company

A047