

Appendix

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-254

Docket No. 50-265

As a result of the inspection conducted on July 9-12, 1985, and in accordance with the General Policy and Procedures for NRC Enforcement Actions, (10 CFR Part 2, Appendix C), the following violation was identified:

Technical Specification 3.2.G.2 states that...with one or more radioactive liquid effluent monitoring instruments inoperable, take the action shown in Table 3.2-5.

Action A, for service water effluent gross activity monitor, in Table 3.2-5 states that...with less than the minimum number of operable channels, releases via this pathway may continue, provided that at least once per 12 hours grab samples are collected and analyzed for beta or gamma activity at an LLD of less than or equal to 10^{-7} uCi/ml.

Contrary to the above, the 12 hour grab samples from both Unit 1 and Unit 2 service water, required about 8:00 p.m. on June 13, 1985, were not collected and analyzed (the service water monitors for both Unit 1 and Unit 2 have remained inoperable since December 19, 1984).

This is a Severity Level V violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

7-30-85
Dated

W D Shafer
W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

8508050222 850731
PDR ADDCK 05000254
G PDR