

APPENDIX A

NOTICE OF VIOLATION

Inspection Service Corporation
P. O. Box 143
Conshohocken, Pennsylvania 19428

Docket No. 030-06265
License No. 37-11636-01

As a result of the inspection conducted on April 9, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

Condition 17 of License No. 37-11636-01 requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in application dated July 29, 1980.

Appendix A, item 4(B), to this application requires radiographers to rope off and post areas where radiography is performed.

Contrary to the above, on April 8, 1985, a radiographer performed radiographic operations on piping in an open area without roping off or posting the radiation area.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Inspection Service Corporation is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.