

APPENDIX A
NOTICE OF VIOLATION

Acutech Medical Labs
Reading, Pennsylvania 19602

Docket No. 030-17837
License No. 37-19529-01

As a result of the inspection conducted on August 20, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

- A. Condition 13 of License No. 37-19529-01 requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in the application dated September 2, 1980.

Item 15.A.7 of this application requires radiation safety surveys of radioisotope facilities be conducted at least weekly.

Contrary to the above, weekly surveys of the radioisotope facilities were not conducted for the weeks ending on January 4, February 8, February 15, May 17, May 31, July 26, and August 2, 1985.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, Acutech Medical Labs is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8510030256 850919
REG1 LIC30
37-19529-01 PDR