

Appendix

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-295

Docket No. 50-304

As a result of the inspection conducted on August 20-23, 27 and 28, 1985, and in accordance with the General Policy and Procedures for NRC Enforcement Actions, (10 CFR Part 2, Appendix C), the following violation was identified:

Technical Specification Section 6.2.B requires that radiation control procedures shall be maintained, made available to all personnel and adhered to.

The licensee's Chemistry Procedure ZCP 531-7, "Performance Test For the Eberline Model SAC-4 Scintillation Alpha Counter," (Revision 0, May 5, 1985), requires that the SAC-4 be taken out of service and Chemistry Supervision be notified if a performance test result falls outside limits defined by the designated logbook.

Contrary to the above requirement: daily performance checks on the SAC-4 during June 1985 were outside the acceptable range on 7 occasions with no evidence that the instrument was taken out of service nor that Chemistry Supervision was notified.

This is a Severity Level V violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

9-27-85
Dated

W.D. Shafer
W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

8510090161 850927
PDR ADOCK 05000295
G PDR