

"OFFICIAL RECORD COPY"

JUL 10 1985

34-197447

✓ Guillermo Velasquez, M.D.
959 Americo Miranda
Reparto Metropolitano
Rio Piedras, Puerto Rico 00921

Gentlemen:

SUBJECT: REPORT NO. 52-21082-01/85-01

Thank you for your response of June 26, 1985, to our Notice of Violation issued on May 28, 1985, concerning activities conducted at your Rio Piedras facility under NRC License No. 52-21082-01. In a telephone conversation with L. Franklin on July 3, 1985, you confirmed that a metal plate had been installed on the inside of the cabinet door, thereby correcting the excessive dose rate violation under 10 CFR 20.105(b)(2). We have evaluated your responses and found that they meet the requirements of 10 CFR 2.201. We will examine the implementation of your corrective actions during future inspections.

We appreciate your cooperation in this matter.

Sincerely,

J. Philip Stohr, Director
Division of Radiation Safety
and Safeguards

bcc: Document Control Desk
Commonwealth of Puerto Rico
✓ L. Cobb, IE

RII

RII

RII

RII

LFranklin:nw
7/7/85

JPotter
7/5/85

KPBarr
7/7/85

JPStohr
7/10/85

8508070598 850710
REG2 LIC30
52-21082-01 PDR

10
IE 07