

APPENDIX A

NOTICE OF VIOLATION

Duquesne Light Company
Beaver Valley Power Station, Unit 2

Docket No. 50-412
License No. CPPR-105

As a result of the inspection conducted on May 23 - June 28, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), published in the Federal Register on March 8, 1984 (49 FR 8583), the following violation was identified:

10 CFR 50, Appendix B, Criterion V requires that activities affecting quality shall be prescribed by procedures and shall be accomplished in accordance with these procedures.

Drawing 12241-BZ-19A-48-OC defines the dimensions, associated tolerances, and other necessary details to properly install pipe support 2SWS-PSST625.

Contrary to the above, and even though the installed support was "final inspected," the relative piping/support centerline dimension of pipe support 2SWS-PSST625 did not conform to that specified on Drawing 12241-BZ-19A-48-OC.

This is a Severity Level IV Violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, Duquesne Light Company is hereby required to submit to this office within thirty days of the date of the cover letter to this Notice, a written statement or explanation in reply including: (1) the corrective steps which have been taken and results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance is achieved. Where good cause is shown, consideration will be given to extending your response time.

OFFICIAL RECORD COPY

8508090089 850718
PDR ADOCK 05000412
G PDR