

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 352

UNIT NAME LIMERICK UNIT 1

DATE MAY 15, 1985

REPORT MONTH APRIL, 1985

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M. ALDEN
ENGINEER-IN-CHARGE
NUCLEAR SECTION
GENERATION DIVISION-NUCLEAR
TELEPHONE (215) 841-5022

| NO. | DATE | TYPE (1) | DURATION (HOURS) (2) | REASON (3) | METHOD OF SHUTTING DOWN REACTOR (4) | LICENSEE EVENT REPORT # (5) | SYSTEM CODE (6) | COMPONENT CODE (7) | CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE |
|-----|--------|-------------|----------------------------|---------------|--|--------------------------------------|-----------------------|--------------------------|---|
| 1 | 850413 | F | 48.3 | B | 4 | N/A | TA | TURBIN | TURBINE VIBRATIONS WERE INVESTIGATED. |

(1)

(2)

(3)

(4)

(5)

- FORCED
- SCHEDULED

REASON

A - EQUIPMENT FAILURE (EXPLAIN)
B - MAINTENANCE OR TEST
C - REFUELING
D - REGULATORY RESTRICTION
E - OPERATOR TRAINING + LICENSE EXAMINATION
F - ADMINISTRATIVE
G - OPERATIONAL ERROR (EXPLAIN)
H - OTHER (EXPLAIN)

METHOD

1 - MANUAL
2 - MANUAL SCRAM
3 - AUTOMATIC SCRAM
4 - OTHER (EXPLAIN)

EXHIBIT G - INSTRUCTIONS
FOR PREPARATION OF DATA
ENTRY SHEETS FOR LICENSEE
EVENT REPORT (LER)
FILE (NUREG-0161)

EXHIBIT I - SAME SOURCE

8508090578 850703
PDR ADOCK 05000352
R PDR