

ENCLOSURE

NOTICE OF VIOLATION

Earth Technology Co., Inc.

License No. 45-16817-01

The following violation was identified during an inspection conducted on September 17, 1985. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

License Condition 14 requires sealed sources containing licensed material be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, the licensee had not tested sealed sources containing Cesium-137 and Americium-241 for leakage and/or contamination since September 1982, an interval greater than six months.

This is a Severity Level IV violation (Supplement VI).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: OCT 03 1985

8510180362 851003
REG2 LIC30
45-16817-01 PDR