

June 21, 1985

United States  
Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Dr. Suite 1000  
Arlington, Texas 76011  
Attn: Mr. Jack E. Whitten

License No. 42-23184-01  
Reference No. 030-28724

Dear Mr. Whitten

Thank you for your cooperation in reissuing of our license, it was received as promised.

A review of the license indicates 2 minor problems that we hope can be easily corrected. The first was the omission of Mr. Richard D. Foss on the license, he was added on our region III license 12-21446-01 amendment no. 1, but left off our region IV license.

The second is on page 2, paragraph 10; and on page 3, paragraph 13. Page 3 indicates that license material under items 10.E. through 10.I. shall be used by, or under the direct supervision and in the physical presence of Richard H. Tanker. Item 10.I. is an AECL Theratron 60 Unit which contains a round source drawer as does items 10.A. through 10.D. Mr. Freeman and Mr. Foss are permitted to perform licensed activities on AECL round drawer machines and only Richard H. Tanker is permitted to work on AECL square drawer machines (items 10.E. through 10.H.). The Theratron 60 Unit is the same as the Theratron 80 with the exception being a 60 cm treatment machine and the Theratron 80 a 80 cm treatment machine.


One last item, and that being we have relocated our office address from 106B McKinney to 610 S. Sherman Suite 106, Richardson, Texas 75081. Our mailing address remains unchanged. This change involved no licensed materials and provides the correct street address for your field inspectors.

8508120038 850715  
REG4 LIC30  
42-23184-01 PDR

USNRC  
License 42-23184-01

We apologize for not having caught these omissions sooner, and if we can provide any further information please feel free to call upon us at any time.

Sincerely,



Richard H. Tanker, Radiation Safety Officer.  
Radiation Therapy Services Inc.

RHT:rj