

**Mailing Address**

Alabama Power Company  
600 North 18th Street  
Post Office Box 2641  
Birmingham, Alabama 35291  
Telephone 205 783-6090

**R. P. McDonald**  
Senior Vice President  
Flintridge Building

85 JUL 26 P10: 27



July 22, 1985

Docket No. 50-348  
Docket No. 50-364

Mr. D. M. Verrelli  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, N.W.  
Suite 3100  
Atlanta, GA 30323

SUBJECT: J. M. Farley Nuclear Plant NRC Inspection of  
May 11 - June 10, 1985

RE: Report Numbers 50-348/85-24  
50-364/85-24

Dear Mr. Verrelli:

This letter refers to the violation cited in the subject inspection report which states:

"The following violation was identified during an inspection conducted on May 11 - June 10, 1985. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.8.1 requires that procedures shall be established, implemented and maintained. Administrative Procedure 35, "General Plant Housekeeping and Cleanliness Control" requires in Section 5.1.9 that flammable liquids will not be stored or left unattended in the auxiliary building, diesel generator building and service water structure at any time.

Contrary to the above, on May 22, 1985, combustible liquids were found unattended in the hot machine shop located in the auxiliary building.

This is a Severity V violation (Supplement 1)."

8508120269 850722  
PDR ADDCK 05000348  
G PDR

IE01

1/0

Mr. D. M. Verrelli  
July 22, 1985  
Page Two

Admission or Denial

The above violation occurred as described in the subject reports.

Reason for Violation

The above violation was caused by personnel error in that the individuals failed to follow procedure.

Corrective Action Taken and Results Achieved

All flammable materials in the hot machine shop were removed or properly stored in flammable material lockers. A search was conducted of all other areas in the auxiliary building and all flammable materials were removed.

Corrective Steps Taken to Avoid Further Occurrences

All Maintenance personnel and System Performance Supervision will be retrained on the requirement of FNP-0-AP-35.

Date of Full Compliance


September 1, 1985

Affirmation

I affirm that this response is true and complete to the best of my knowledge, information and belief.

The information contained in this letter is not considered to be of a proprietary nature.

Yours very truly,



R. P. McDonald

RPM:sam

cc: File