



Carolina Power & Light Company

Brunswick Steam Electric Plant

P. O. Box 10429

Southport, NC 28461-0429

August 2, 1985

05 AUG 5 8:55

FILE: B09-13510C

SERIAL: BSEP/85-1385

Dr. J. Nelson Grace, Administrator
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street NW
Atlanta, GA 30323

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1

DOCKET NO. 50-325

LICENSE NO. DPR-71

SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8 AND
PURSANT TO TECHNICAL SPECIFICATION 6.9.2 (1-SR-85-7)

Dear Dr. Grace:

During an ongoing Unit 1 refueling/maintenance outage, fire barrier LCOs were initiated, respectively, on July 4 and 8, 1985, for fire doors 303 and 301 of the Unit 1 Reactor Building. These doors provide personnel access to the Reactor Building 50' elevation from the roof area of the Units 1 and 2 common Radwaste Building and from the Unit 1 Turbine Building. The subject LCOs were initiated to allow repair of problems affecting closing of door 303 and weather stripping, threshold seal, and frame stop problems affecting door 301. Respectively, on July 11 and 15, 1985, the seven-day specified time frames of the subject LCOs were exceeded. Until the problems affecting the doors are resolved, appropriate stationed fire watches will be maintained.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

MJF/ag

Enclosure

cc: NRC Document Control Desk

8508120332 850802
PDR ADOCK 05000325
S PDR

IE22

~~1119~~