



Docket No. 50-346

License No. NPF-3

Serial No. 1196

October 15, 1985

JOE WILLIAMS, JR.
Senior Vice President - Nuclear
(419) 249-2300
(419) 249-5223

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
United States Nuclear Regulatory Commission
Washington, D.C. 02555


Dear Mr. Denton:

Attached, for your information, are two assessment reports commissioned by Toledo Edison.

1. Assessment of Actions at Davis-Besse Resulting from June 9, 1985 Loss of Feedwater Events.
2. Independent Assessment of the Davis-Besse Quality Assurance Program.

Toledo Edison is currently studying the conclusions and recommendations presented in these reports. Many of the items are currently being addressed. Those remaining items, not currently being addressed, will be resolved in a manner commensurate with their importance.

Very truly yours,



JW:RFP:DJS:lah

cc: DB-1 NRC Resident Inspector

Mr. James G. Keppler
Regional Administrator

8510220368 851015
PDR ADOCK 05000346
S PDR

