



TOLEDO  
EDISON

File: RR 2 P-8-85-09  
E 2.40.1.1.3  
G85 796AL

October 16, 1985

Technical Records Section  
Ohio Environmental Protection Agency  
P.O. Box 1049  
Columbus, OH 43216-1049

Gentlemen:

Attached is a copy of the September, 1985 Wastewater Report for Davis-Besse Nuclear Power Station, Unit No. 1.

Electric power to the Davis-Besse Beach Sampling Station was lost due to damage in the structure's circuitry panel. Power was restored and sampling reinstituted on September 30, 1985. A letter of notification was sent to Ohio EPA on September 30, 1985.

Also, the second BOD<sub>5</sub> analysis for Outfall 601 (Sewage Treatment Discharge) was not performed due to a procedural deficiency. The procedure has been revised.

Yours truly,

L. F. Storz  
Plant Manager

Davis-Besse Nuclear Power Station  
(419) 249-5000, Ext. 589

LFS/PJM/ym1  
encl. (2 copies)  
cc: W. Rogers, NRC Resident Inspector  
J. F. Storz, NRC  
J. Sullivan  
J. Scott-Wasilk  
A. Gephart

8510240039 851016  
PDR ADOCK 05000346  
R PDR

IE25  
11