

0841

CAPITAL X-RAY SERVICES, INC.

P. O. BOX 3264
TULSA, OKLAHOMA 74101
TELEPHONE 918 583-5797

June 16, 1983

'83 JUN 17 P3:44

USNRC Lic. #35-11114-01
Control No. 14431
030-04933

Mr. Joseph C. Wang
United States Nuclear Regulatory Commission
Material Licensing Branch
Division of Fuel Cycle and Material Licensing
Washington, D.C. 20555

Mr. Wang:

This letter is in reference to our phone conversation of June 16, 1983 and your request for additional information to support Capital X-Ray Services, Inc's application for amendment to License #35-11114-01.

Our conversation related to two (2) necessary procedural changes:

1. The use of radiation collimation devices for all radiographic exposures (Ir 192 & Co 60) performed within the Shielded Radiographic Facility.
2. The restricting of the maintenance or repair of any component, including the roof, of the Shielded Radiographic Facility to only those times when a Sealed Source (Ir 192 & Co 60) is not being used within the facility.

These two (2) procedural changes shall be amended in the following manner:

Item #1 OPERATING, CAUTION AND EMERGENCY PROCEDURES - SUPPLEMENT;
SHIELDED RADIOGRAPHIC FACILITY:

Section S-12g; Page 4-6e, Radiation Collimation/Shielded Devices

This section shall be immediately amended to mandatorily require the use of radiation beam collimation devices for all radiographic exposures (Ir 192 & Co 60) performed within the Shielded Radiographic Facility.

Note: NO UNCOLLIMATED (IR 192 & CO 60) RADIOGRAPHIC EXPOSURES SHALL BE PERFORMED WITHIN THE SHIELDED RADIOGRAPHIC FACILITY.

8508120531 850612
REG4 LIC30
35-11114-01 PDR

COPY SENT REGION *IV*

Joseph C. Wang

-2-

June 16, 1983

Item #2 OPERATING, CAUTION AND EMERGENCY PROCEDURES - SUPPLEMENT;
SHIELDED RADIOGRAPHIC FACILITY:

Section S-12o; Page 15-6e, Maintenance, Repair and Audible Alarms Testing-
Shielded Radiographic Facility


This section shall be immediately amended such that the maintenance or repair of any item relating to the Shielded Radiographic Facility, including the facility roof and the walls, shall not be performed at any time when a Sealed Source (Ir 192 & Co 60) is being employed within the facility.

The maintenance or repair of any item relating to the Shielded Radiographic Facility shall be performed only by, or under the immediate supervision of:

1. The Radiation Safety Officer
2. The Assistant Radiation Safety Officer
3. The Radiographic Equipment Manager


Mr. Wang, if you have any questions concerning this additional procedural information, please notify me.

Sincerely,



George W. Johnson
Radiation Safety Officer
Capital X-Ray Services, Inc.
2133 South 49th West Avenue
Tulsa, Oklahoma 74107

I hereby Certify that the information contained herein, is true and correct to the best of my knowledge and belief.



Notary Public

My Commission Expires 10-4-84