


# MIDCO

MID-CONTINENT WIRELINE SERVICES

June 20, 1984

U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



Attn: Mr. Jerry Everett  
Material Licensing Branch

Re: Renewal of License No. 35-19041-1

Dear Mr. Everett:

We have received notice that the above numbered byproduct material license will expire on July 31, 1984. We have reviewed our radiation program and submit herewith a renewal application together with our new Operating and Emergency Procedures Manual and our check in the amount of \$700.00 to cover the licensing fee.

We have reviewed the previously submitted materials as referenced in our license. Please omit reference to applications of 5/18/79 and 9/17/79 and letters of 9/2/81 and 10/29/82, as the information submitted with them is no longer accurate or has been incorporated into the new application and procedures submitted herewith. We do, however, wish to reference the Training and Safety Manual submitted 5/15/81, as the basis for our in-house training program, and we enclose herewith an up-dated Page 1 giving criteria for the training. Also enclosed is a Memo to File which we will use to document our training files. Keith E. Moon of Support Consultants will be the instructor for in-house training.

We have closed our Enid, Oklahoma station, and have deleted it from this application. The Enid facility was not used for storage of radioactive materials. When radioactive materials were required for operations from the Enid station, they were sent from Oklahoma City and returned to Oklahoma City upon completion of the job. We have surveyed the facility and found no residual contamination.

RECEIVED BY LFMB	
Date	6/29/84
Log	June 6 II
By	Brown
Orig To	
Action Compl	7/2/84

Applicant	3779
Check No	4700-5A
Amount, Fee Category	Renewal
Type of Fee	6/29/84
Date Check Rec'd	Brown
Received By	
8508120612 850725	
REG4 LIC30	
35-19041-01 PDR	
Postmarked 6/29/84	

405/691-3911  
405/234-6101

P.O. BOX 6322  
P.O. BOX 10006

MOORE, OKLAHOMA 73153  
ENID, OKLAHOMA 73702

60325

Page Two  
U.S. NRC - Region IV  
June 20, 1984

Please renew our license so that we may continue well logging operations using radioactive materials. Our operations have not changed since the license was issued, however, due to the downturn in the oil and gas industry, the use of our two AmBe sources has been greatly reduced and use of radioactive tracer materials is only occasional. I will continue to serve as Radiation Protection Officer and copies of my resume and certificate as previously submitted are attached. If you have any questions regarding this submittal, please contact me or our consultant, Keith E. Moon, who has assisted us in the preparation of this submittal. Mr. Moon is authorized to represent us regarding the renewal of our license.

Sincerely,

*Robert C. Bales*

Robert C. Bales  
Operations Manager and  
Radiation Safety Officer

pm  
Enclosures

cc: Keith Moon