



Portland General Electric Company
Trojan Nuclear Plant
P.O. Box 439
Rainier, Oregon 97048
(503) 556-3713

RECEIVED
NRC

1985 JUL 10 PM 12:25

REGION V I&F

July 3, 1985
WSO-440-85

Mr. John B. Martin
Regional Administrator, Region V
US Nuclear Regulatory Commission
1450 Maria Lane, Suite 210
Walnut Creek, CA 94596-5368

Dear Sir:

Special Report

Limiting conditions for operation (LCO) 3.7.8.2 of the Trojan Technical Specifications requires that a special report be provided if a continuous fire watch is not established within 1 hour when one or more of the required spray, sprinkler and/or deluge systems are inoperable.

A continuous fire watch was established while modifications involving welding were being performed on deluge systems 18 and 19. The continuous fire watch remained on duty 30 minutes after completion of the welding. At that time, with the deluge systems still inoperable, operations personnel incorrectly established a one-hour roving fire patrol rather than a continuous fire watch. The discrepancy was noticed during a supervisory tour approximately two hours later and a continuous fire watch was immediately established.

Sincerely,

W. S. Orser
General Manager

SAB
WSO/SAB/RES:pat

c: Distribution
File: 93.24a

8508130189 850703
PDR ADDCK 05000344
S PDR

110
1E28