



Portland General Electric Company
Trojan Nuclear Plant
P.O. Box 439
Rainier, Oregon 97048
(503) 556-3713

50-344
October 11, 1985
WSO-612-85

Mr. John B. Martin
Regional Administrator - V
U.S. Nuclear Regulatory Commission
1450 Maria Lane Suite 210
Walnut Creek, California 94596-5368

Dear Sir:

Limiting Conditions for Operations (LCO) 3.7.9 of the Trojan Technical Specifications require that a special report be provided if certain fire barrier penetrations become nonfunctional and cannot be returned to functional status within seven days.

During construction activities on September 19, 1985, on the forty-five foot level of the Trojan Control Building, portions of the masonry used for fire protection on structural steel was removed from two support columns. The required compensatory actions were performed. The protective encasement will be restored during the course of the construction activities with an estimated completion date of November 15, 1985.

Sincerely,

W. S. Orser
Manager,
Trojan Nuclear Plant

WSO/JKA/SAS:jdw

c: LER Distribution

8510280214 851011
PDR ADOCK 05000344
S PDR

RV

1E01 110

REGION VISE

1985 OCT 16 AM 11:41

RECEIVED
NRC