

APPENDIX B

NOTICE OF DEVIATION

Boston Edison Company
Pilgrim Nuclear Power Station

Docket No. 50-293
License No. DPR-35

As a result of the inspection conducted on June 13, 1985 - July 15, 1985, and in accordance with the NRC Enforcement Policy, 10 CFR Part 2, Appendix C, 49 FR 8583 (March 8, 1984), the following deviation was identified:

The Inservice Testing Program (ISI) submitted to the NRC in a letter dated April 13, 1979 required that the setpoint on a vacuum relief valve, VRV-9066, in the high pressure coolant injection (HPCI) system, be tested every five years. The licensee committed to implement this program on August 1, 1979. The second 10-year IST program submitted to the NRC in a letter dated July 11, 1983, which the licensee committed to implement in the third quarter of 1983, as revised in a letter dated February 14, 1984, required that the following tests be conducted quarterly:

<u>System</u>	<u>Valve</u>	<u>Test</u>
HPCI	2301-8	Stroke time to close position
	VRV-9066	Stroke time to open position
Diesel Oil Transfer	1 in. No. 223 (2 valves)	Stroke to close position
	Foot-Val A and B	Stroke to close position

Contrary to the above, on June 24, 1985, the VRV-9066, 2301-8, No. 223, and Foot-Val A and B valves had not been tested in the manner indicated.

Boston Edison Company is hereby requested to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have taken and the results achieved; (2) corrective steps which will be taken to avoid further deviation; and (3) the date when corrective actions will be complete. Where good cause is shown, consideration will be given to extending this response time.

8508130375 850806
PDR ADOCK 05000293
Q PDR