

Log # TXX-4600
File # 10110
TEXAS UTILITIES GENERATING COMPANY
SKYWAY TOWER - 400 NORTH OLIVE STREET, L.B. 81 - DALLAS, TEXAS 75201

WILLIAM G. COUNCIL
EXECUTIVE VICE PRESIDENT

October 16, 1985

Mr. R. P. Denise, Director
Division of Reactor Safety and Projects
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION
DOCKET NOS. 50-445 AND 50-446
AUXILIARY FEEDWATER SYSTEM
QA FILE: CP-85-32, SDAR-193

OCT 21 1985

Dear Mr. Denise:

On August 27, 1985, we verbally notified your Mr. T. Westerman of a deficiency regarding the potential loss of control capability of the feedwater regulating valve due to the valve's power supply being located in the cable spread room. We have submitted an interim report logged TXX-4567, dated September 24, 1985.

We have completed our investigation and concluded that the matter is not reportable under 10 CFR 50.55(e). Records supporting this determination are available for your inspector's review at the CPSES site.

Very truly yours,

W. G. Council

W. G. Council

By: *J. S. Marshall*
J. S. Marshall
Licensing Supervisor

JCH/grr

c - NRC Region IV (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

85-955
8510280500 851016
PDR ADOCK 05000445
S PDR

A DIVISION OF TEXAS UTILITIES ELECTRIC COMPANY

JE-27
140