



**Northeast
Utilities System**

Millstone Offices • Rope Ferry Rd., Waterford, CT

P.O. Box 128
Waterford, CT 06385-0128
(203) 447-1791

JAN 14 1997

Docket No. 50-245

50-336

50-423

B16149

US Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555


**Millstone Nuclear Power Station Unit Nos. 1, 2 and 3
10 CFR 21 Report Concerning Cracked Fuse Ferrule Defects (NRC Event #31371)**

In a letter dated December 13, 1996, Northeast Nuclear Energy Company (NNECO) transmitted to the NRC a notification of a Substantial Safety Hazard (SSH) at the Millstone Nuclear Power Station regarding cracked fuse ferrules. NNECO has identified an administrative error in Attachment 1 of the letter which detailed our commitments regarding this issue. In section (vii)(b) of the letter NNECO committed that Millstone Design Engineering Departments would develop a process to check and replace the cracked fuses delineated in Section (ii)(a) of the report. In Attachment 1 the referenced section for the fuses we would address was incorrectly identified as Section (ii)(b). A corrected copy of the commitments associated with the letter is provided in Attachment 1.

Should you have any questions regarding this submittal, please contact Mr. James M. Peschel at (860) 437-5840.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY


Jay K. Thayer
Recovery Officer

Engineering and Support Services

9701230418 970114
PDR ADOCK 05000245
S PDR

JE19
11

cc: H.J. Miller, Region 1 Administrator
W.D. Travers, Dr., Director Special Projects
A.C. Cerne, Senior Resident inspector, Millstone Unit No. 3
J.W. Andersen, NRC Project Manager, Millstone Unit No. 3

Docket No. 50-245

50-336

50-423

B16149

Attachment 1

Millstone Nuclear Power Station Nos. 1, 2, and 3

January 1997

Enclosure
List of Regulatory Commitments

The following table identifies those actions committed to by NNECO in this document. Any other actions discussed in the submittal represent intended or planned actions by NNECO. They are described to the NRC for the NRC's information and are not regulatory commitments. Please notify the Manager - Nuclear Licensing at the Millstone Nuclear Power Station Unit No. 3 of any questions regarding this document or any associated regulatory commitments.

Commitment		Committed Date or Outage
B16030-1	A listing of safety related distribution fuses affected by this issue, and their locations, will be prepared.	May 31, 1997
B16030-2	A plan to check and replace cracked fuses as delineated in Section (ii)(a) will be developed for each Millstone Unit.	January 31, 1997
B16030-3	Issue Purchase Orders for replacement fuses	January 31, 1997
B16030-4	A verification of field storage locations will be completed to determine if fuses have been returned to the warehouse.	January 31, 1997