

JUN 11 1985

Docket No. 030-21266
Control No. 103874

J. H. Maxymillian, Inc.
ATTN: Anthony J. Simonelli, RSO
1801 East Street
Pittsfield, Massachusetts 01201

Gentlemen:

This is in reference to your application dated May 22, 1985, for a byproduct material license. In order to continue our review, we need the following additional information:

1. Please identify the exchange frequency of your personnel monitoring devices. The exchange frequency for film badges should not exceed intervals of one month and thermoluminescent dosimeter (TLD) should not exceed three months.
2. When performing maintenance, which involves removal of the source rod, you should have available a calibrated and operable survey meter capable of reading up to 200mR/hr. Please confirm that this type of meter will be available and verify that the individual performing maintenance (cleaning) has been properly trained in the procedure and the use of a survey meter.

We will continue our review upon receipt of this information. Please reply in duplicate to my attention at the Region I office and refer to Mail Control No. 103874.

Sincerely,

Original Signed By:
John E. Glenn

John E. Glenn, Ph.D., Chief
Nuclear Materials Safety Section B
Division of Radiation Safety
and Safeguards

8508140285 850724
REQ1 LIC30
20-20853-01 PDR

RI:DRSS *SA* RI:DRSS
Joustra/djh *SA* Glenn

6/5/85

6/10/85

OFFICIAL RECORD COPY

938 - 0001.0.0
06/05/85

ML10