

ENCLOSURE 1

NOTICE OF VIOLATION

Carolina Power and Light Company
Brunswick 2

Docket No. 50-324
License No. DPR-62

The following violation was identified during an inspection conducted on September 1-30, 1985. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.8.1.a requires that written procedures listed in Appendix A of Regulatory Guide 1.33, November 1972 be implemented. Item A.3 of Appendix A requires procedures for equipment control. Equipment control procedure OI-13 step 4.5 requires all valves be maintained in position required for the OP valve lineup. OP-46 requires valves 2-RNA-V202 and V203 to be in the open position.

Contrary to the above, Technical Specification 6.8.1.a was not implemented in that valves 2-RNA-V202 and V203 were not maintained open on September 4, 1985. The valves were inadvertently closed by an auxiliary operator while hanging clearance No. 2-1107.

This is a Severity Level V Violation (Supplement I)

Pursuant to 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: OCT 21 1985

8511010412 851021
PDR ADOCK 05000324
Q PDR