

BOSTON EDISON COMPANY  
800 BOYLSTON STREET  
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON  
SENIOR VICE PRESIDENT  
NUCLEAR

August 7, 1985  
BECO Ltr. #85-142

Mr. Stewart D. Ebner, Director  
Division of Reactor Safety  
U.S. Nuclear Regulatory Commission  
Region I - 631 Park Avenue  
King of Prussia, PA 19406

License No. DPR-35  
Docket No. 50-293

Subject: Followup Information Relating to INC 81-22-01

Reference: Combined NRC Inspections 81-18 and 81-22

Dear Mr. Martin:

Per Boston Edison Company's telephone conversation on 7/30/85 with Mr. Jack Durr of your office, we are providing you with the following information relating to Item of Non-Compliance 81-22-01:

In order to enhance the affected Station operating procedures to the point where those procedures will provide the user adequate technical guidance and Tech. Spec. section references, the below-listed activities will be funded, staffed, and completed as follows:

<u>Activity Description</u>	<u>Scheduled Completion Date</u>
Revise procedures for D4, D5, D6, Y1, Y2, and D19 to more clearly indicate equipment affected by the individual breakers.	12/31/85
Complete E-203 walkdowns and issue Discrepancy packages to the Nuclear Engineering Dept. for disposition.	7/31/86
Revise all affected procedures to include:	9/30/86
1) Applicable Technical Specifications	
2) Walkdown-Observed Configuration Changes	
3) Component Details	

8508150185 850807  
PDR ADOCK 05000293  
G PDR

RECEIVED-REGION I  
1985 AUG -9 PM 2:56


10  
1E 01

BOSTON EDISON COMPANY

Mr. Steward D. Ebnetter  
U.S. Nuclear Regulatory Commission  
August 7, 1985  
Page Two

We trust that this information will provide the details and content required. However, if you have any further questions regarding these issues, please do not hesitate to contact me.

Very truly yours,

A handwritten signature in dark ink, appearing to read "W.D. Harrington". The signature is written in a cursive, somewhat stylized script.

W. D. Harrington