

D C D

January 23, 1997

Ed Graham
 Managing Partner
 Dayton X-Ray Company/d.b.a.
 U.S. Inspection Services
 705 Albany Street
 Dayton, OH 45408

SUBJECT: NOTICE OF VIOLATION DATED NOVEMBER 19, 1996

Dear Mr. Graham:

This acknowledges receipt of your letter dated December 18, 1996, in response to our letter dated November 19, 1996, transmitting a Notice of Violation.

We have reviewed your corrective actions, which appear to be adequate, and have no further questions at this time. These corrective actions will be examined during a future inspection.

Sincerely,

Original Signed by B. J. Holt

Cynthia D. Pederson
 Cynthia D. Pederson, Director
 Division of Nuclear Materials Safety

License No.: 34-06943-01
 Docket No.: 030-05731

bcc w/ltr dtd 12/18/96: PUBLIC

DOCUMENT NAME: G:\LTRS2LIC\MTLS\030\97305731.L01

To receive a copy of this document, indicate in the box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

OFFICE	DNMS/RIII	C	DNMS/RIII	C	DNMS/RIII				
NAME	RGATTONE/jaw	SB	JMADERA	km	CPEDERSON	SB			
DATE	01/22/97		01/27/97		01/23/97				

OFFICIAL RECORD COPY

9701280211 970123
 PDR ADOCK 03005731
 C PDR

IE07

US INSPECTION
SERVICES
Formerly Dayton X-Ray
Since 1938

December 18, 1996

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington D.C. 20555

Re: Reply to Notice of Violation

This letter is in response to your letter; subject: NRC Inspection and Notice of Violation dated November 19, 1996.

- Violation 1. Ted Liebig, the radiographer, misinterpreted the NRC requirements of surveillance in 10CFR34.23.
- Violation 2. The Overpack was recently painted and the radiographer did not reapply labeling.
- Violation 3. The radiographer failed to check Alarm Ratemeter.
- Violation 4. The Amersham Model 660B Camera was brand new.

For Corrective Action on Violations 1,2 and 3 Ted Liebig was given 8 hours of additional radiation safety training and was given a written test on November 4, 1996. In addition, Ted Liebig was given a three day suspension without pay.

Solutions to the Violations 1,2 and 3 shall be a more focused auditing with increased attention to source shipment, source monitoring and personal protection equipment. In the past we have concentrated more on source surveys, area surveys, source sign outs, and operating and emergency procedures.

For corrective action on Violation 4. The camera in question, camera S/N B3214, was shipped as a new camera in a loaded condition from Amersham. It was an oversight on our part for not catching a missing RQ Label.

The importance of the RQ Label has been addressed with all of our radiographers.


Even though we feel these are isolated instances, we went over each violation in a meeting with all of our radiographers.

9612230119

page 2

The documentation of all corrective actions were implemented as of November 4, 1996. If you have any further questions, please feel free to call.

Sincerely,

A handwritten signature in cursive script that reads "Chris Small".

Chris Small
General Manager
License No. 34-06943-01
Docket No. 030-05731

cc: Regional Administrator
Region III
801 Warrensville Road
Lisle, IL 60532-4351

CS/hc

violat.doc